FORM 9 CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

Construction Act

THE REGION MUNICIPALITY OF HALTON - TOWN OF OAKVILLE
(County/District/Regional Municipality/Town/City in which premises are situated)
1151 BRONTE ROAD - OAKVILLE, ONTARIO - L6M 3L1
(street address and city, town, etc., or, if there is no street address, the location of the premises)
This is to certify that the contract for the following improvement: HALTON REGIONAL CENTRE PROJECT 2 - SITE DEVELOPMENT AND OPTIMIZATION (RENOVATIONS & ADDITION - WEST BLOCK, EAST BLOCK, MAIN BLOCK & HALTON CHILD CARE CENTRE)
(short description of the improvement)
to the above premises was substantially performed onDECEMBER_21, 2023 (date substantially performed)
Date certificate signed: DECEMBER 21, 2023
T. 6h
(payment certifier where there is one) (owner and contractor, where there is no payment certifier) TOM KYLE
(STANTEC ARCHITECTURE LTD.)
Name of owner: THE REGIONAL MUNICIPALITY OF HALTON
Address for service: 1151 BRONTE ROAD - OAKVILLE, ONTARIO - L6M 3L1
Name of contractor: MATHESON - BDA INC.
Address for service: 205 INDUSTRIAL PARKWAY NORTH - UNIT 5 - AURORA, ONTARIO - L4G 4C4
Name of payment certifier (where applicable):TOM KYLE (STANTEC ARCHITECTURE LTD.)
Address: 100-401 WELLINGTON STREET WEST - TORONTO, ONTARIO - M5V 1E7
(Use A or B, whichever is appropriate)
A. Identification of premises for preservation of liens:
PART OF LOT 30 - CONCESSION 2 S.D.S TOWN OF OAKVILLE - REGIONAL MUNICIPALITY OF HALTON
(if a lien attaches to the premises, a legal description of the premises, including all property identifier numbers and addresses for the premises)
B. Office to which claim for lien must be given to preserve lien:
(if the lien does not attach to the premises, the name and address of the person or body to whom the claim for lien must be given)

HRC PROJECT 2 - SUB PERF CALCULATION ANALYSIS (NOV. 28, 2023)

1: ORIGINAL CONSTRUCTION VALUE

 Original contract
 \$46,944,000.00

 Changes
 \$21,273,435.64

 Current Construction Value
 \$68,217,435.64

Substantial Performance Calculation:

 3% of first \$500,000
 \$15,000.00

 2% of next \$500,000
 \$10,000.00

 1% of remainder
 \$681,924.36

 Total
 \$706,924.36

Substantial performance

value full contract \$67,510,511.28

2: PROPOSED REVISED CONTRACT VALUE

Proposed Deferred Values

Cash Allowances \$216,019.53

Total \$216,019.53

New Construction Value

with deferred items \$68,001,416.11

3: REVISED SUB PERF CALCULATION

Substantial Performance Calculation:

 3% of first \$500,000
 \$15,000.00

 2% of next \$500,000
 \$10,000.00

 1% of remainder
 \$679,764.16

 Total
 \$704,764.16

4: REVISED SUB PERF VALUE

Substantial Performance Value \$67,296,651.95

5: REVISED SUB PERF CALCULATION SUMMARY

 Total progress to date (OCT 31)
 67,968,412.67

 Total Deficiencies (NOV 17)
 485,600.00

 TOTAL PROGRESS VALUE FOR SP
 67,482,812.67

TOTAL DEFCIENCIES - INCOMPLETE WORK (NOV 21 2023)

ARCH
EAST BLOCK \$282,300.00
HCCC 44,900.00
WEST 23,200.00
MAIN 12,500.00

CIVIL

35,500.00

LANDSCAPE

37,750.00

STRUCT

0

MECH

26,850.00

ELECT

22,600.00

TOTAL \$485,600.00



CERTIFICATE FOR PAYMENT NO. 47.0

To Owner: THE REGIONAL MUNICIPALITY OF Contractor: MATHESON-BDA INC.

HALTON

1151 BRONTE ROAD 205 Industrial Parkway North, Unit 5

OAKVILLE, ONTARIO Aurora, Ontario

L6M 3L1 L4G 4C4

Project HRC Project 2 - Site Redevelopment and Issue Date: Friday, November 17, 2023

Optimi

Project No: 1400-16076-4 - 08-10

Stantec Architecture Ltd.

This is to certify, in accordance with the contract dated 2/4/2020, the Contractor MATHESON-BDA INC.

has completed work and delivered products to the place of work, and is entitled to a payment of

FIVE HUNDRED EIGHTEEN THOUSAND EIGHT HUNDRED NINETEEN DOLLARS AND SEVENTY FIVE CENTS

Original Contract Price	9	\$46,944,000.00	Contractor's	47R4
Collect Cash Allowance	\$2,065,000.00)	Application	
Balance of Allowance Remaining to Date	\$216,019.53	3	Number	
Change Orders Issued to Date	\$	\$21,273,435.64	Work Period	
Revised Contract Price to Date	\$	668,217,435.64	From	10/1/2023
Value of Work Completed to Date	\$	67,968,412.67	То	10/31/2023
Previous Claim Amount	\$	67,452,533.43		nWfh]Z]YX`]g`giV^YWh`hc cibh`cZ`Ubm`]Yb`cZ`k\]W
Value of Work for Period		\$515,879.24	mci `\Uj Y`fYWY]j YX`k	
Value of Work for Period (Less Holdback)		\$464,291.32	h\Y`dUnYY`bUa YX`]b	reinjov robox jgdoliov rie oʻjh⁄≔ggiUbWrdUna Ybh'UbX Ncih'dfY^iX]Wrhc'Ubm
TOTAL WARRANTY SECURITY HOLDBACK (SEF	PTEMBER)	-\$5,158.79 \$0.00	Webhfunti'	'cf'7cbhfWMcf'i bXYf'h\Y
.75 TOTAL NET THIS APPLICATION HST @ 13%		\$459,132.52 \$59,687.23	g\U```bch'VY'hU_Yb'`U h\Y'5fV\]hYV h i\Ugʻa	g:7Yfh]Z]WUhY:Zcf:DUmaYbh Lg:U:fYdfYgYbhUh]cb:h\Uh UXY:UbmiYl:Ua]bUh]cb:hc Zcf:k\Uh:difdcgY:h\Y
TOTAL AMOUNT PAYABLE THIS CERTIFICATE		\$518,819.75	7cbhfUMhcf`\UgʻX]gM]a dcgYX`cb`\]a `Vm	<pre>XUf[Y'h\Y'cV`][Uh]cbg `Uk 'i bXYf'h\Y'K cf_YfÑg</pre>
Calculation of Holdback				cf cn\yf udd jywy y `]UbWrk]h\rk\]W(a Um YfgcbU`m`]UV`Y'Zcfrh\Y
Deficiency Retainange at Substantial Performance		\$0.00	7cbhfUMhcfÑg:XYZUi`	h"
Holdback @ 10.000% TOTAL WARRANTY SECURITY HOLDBACK		\$6,796,841.27 \$765,684.13		
AMOUNT PREVIOUSLY RELEASED AMOUNT RELEASED THIS CLAIM		\$907,211.11 \$0.00		
TOTAL RELEASED TO DATE		\$907,211.11	Stantec Architectu	
Total holdback		\$6,655,314.29	Toronto, ON M5V 1E	et West, Suite #100 E7
7. 6h			Tel: 416.596.6666 Fax: 416.596.7892 Web: www.stantec.	com
rom kyle				



CERTIFICATE FOR PAYMENT NO. 47.0

Distribution:

<u>Representing</u>	<u>Fax Number</u>
THE REGIONAL MUNICIPALITY OF HALTON	(905) 825-6000
THE REGIONAL MUNICIPALITY OF HALTON	(905) 825-6000
THE REGIONAL MUNICIPALITY OF HALTON	(905) 825-6000
MATHESON-BDA INC.	(000) 000-0000
STANTEC ARCHITECTURE & CONSULTING	(416) 596-7892
STANTEC ARCHITECTURE & CONSULTING	(416) 596-7892
STANTEC ARCHITECTURE & CONSULTING	(416) 596-7892
STANTEC ARCHITECTURE & CONSULTING	(416) 596-7892
STANTEC ARCHITECTURE & CONSULTING	(905) 474-9889
STANTEC ARCHITECTURE & CONSULTING	(416) 596-7892
STANTEC ARCHITECTURE & CONSULTING	(416) 596-7892
STANTEC ARCHITECTURE & CONSULTING	(416) 596-7892
STANTEC ARCHITECTURE & CONSULTING	(416) 596-7892
	THE REGIONAL MUNICIPALITY OF HALTON THE REGIONAL MUNICIPALITY OF HALTON THE REGIONAL MUNICIPALITY OF HALTON MATHESON-BDA INC. STANTEC ARCHITECTURE & CONSULTING

STANTEC CIVIL - MECHANICAL - ELECTRICAL DEFICIENCIES & INCOMPLETE WORK LIST

John More 2 Note, here processes and excellences through our but of 2. It is not received processes of control angle of the color of programs of the color of	Block	Room Number	Discipline	Deficiency Description	\$ Assig	gned by CA
the Millord Control States Security copys of an interpretate power to be manufacted and where 2. 5 50			Mech	Multiple sprinkler heads within stairwells, garage and storage rooms have upright heads that require guards provided throughout.	\$	1,250.00
Month Mech Mech Mech Mech Mech Mech Mech Mec						1,250.00
Med. Med. Med. Med. Med. Med. Med. Med.						500.00
Month						1,000.00
Name Need Room Merch March Machine Section Services and S	East					2,500.00
Machine Methodology of the processor of	Main	Mach Poom				500.00
Mech Dech Dech Dech Dech Dech Dech Dech D	IVIdIII					5,000.00 500.00
Worth Note						500.00
Moch						500.00
Moch Moch Store draws within garage are traping in clamps and construction debts removed. Moch Moch Are last detected of a scena for intCC level 3 to be checked and scaled as recessary corridor CC 4-06. Moch Moch Moch Moch Moch Moch Moch Moch						250.00
Mech Mich Oronectic water prings to be involved Solveni II. Mech Mech Mich Reprings the Solveni II. Mech Mech Mich Reprings the Solveni II. Mech Mech Mech Reprings the Solveni II. Mech Mech Mech Mech Reprings the Solveni II. Mech Mech Mech Mech Mech Mech Mech Mech						500.00
Mech						500.00
Mech Nech						250.00
MeCC MeCh MeCh MeCC MeCh MeCC Secretarial requires received professional provided. \$ 25					\$	1,500.00
Meth			Mech	Coil RTU-5 has minor damage coil requires combed.	\$	250.00
1.28	HCCC		Mech	HCCC roof exhaust fans require identification provided.	\$	500.00
12.83 Mech	HCCC		Mech	AC-6 HCCC roof flashing requires resealed potential leak.	\$	250.00
1.58 1.58 Mech	East	E1-28	Mech	Exposed ductwork within records room E1-28 requires canvas wrap and identification applied.	\$	1,000.00
1.07, 61-08 Meth Sodurant ductwork, pipe, fluth tangers pipe hargers to be removed even 1 Seat block parage area, £1-07, £1-08 5 5.05						100.00
Man M3-07 Meth Prevention state to be removed condrol MS-07 S 25						250.00
East 1-38 Morch Fire hose cabmet requires properly supported parking garage E1-38 S 5 5 5 5 5 5 5 5 5						1,500.00
East 22-73 Metch Nacher recom Metch Vasciner recom A.C. units have perdominent stope to be adjusted level. 5 25 25 25 25 25 25 25						250.00
East 2-17						500.00
Sext						500.00
Sect						250.00
West W-Step 20e8 Sect Upflit in W-Step 20e8 Sect						5,000.00 1,000.00
West						
West Elect Door security security does not terminated \$ 1.50 Main M2-66, M2-03, M2-03 Elect Door M2-06, M2-03, M2-03 M2-03, M2-03 M2-03, M2-03 M2-					7	100.00 500.00
West Control Door Security at security doors not complete \$ 1,00 Main M2-70 Elect Door M2-20 As 2-M2-3 M2-10 has exposed junction box with wires sticking out \$ 1,50 Main M3-79 Elect M2-19 needs core plates on the exposed junction box \$ 1,50 Main M3-19 Elect M2-19 needs core plates on the exposed junction box \$ 1,00 Main M3-10 Telect M3-10 Security M3-10 Securi						500.00
Main M2-06, M2-03, M2-03 Elect Door M2-06, M2-03, M2-01 has espoced junction box with wires sicking out of the junction box \$ 1.50 Main M2-19						1,000.00
Mani M-70 Elect Door M2-70 has multiple wires sticking out of the junction box						1,500.00
Main M2-19						500.00
Main M3-02, M3-01. Elect M3-11 an sumptiple exposed wires sticking out of door hardware. \$ 1,00 Main M3-03, M3-04, M3-05. Elect M3-11 an sumptiple exposed still sear and missing light wirthch covers. \$ 2,15 854 E4-11. Elect E4-12 bett E4-14 bett E4-15 bett E4-14 bett E4-						100.00
Main						1,000.00
Main M3-03, M3-04, M3-05 Bect M3-03, M3-04, M3-05 door hardware has exposed wring S 1,50				, ,		2,000.00
East E4-11 Sect 64-41 Door hardware incomplete, wires sticking out 5 \$ 5.55 East E4-84 Sec 44-73 Dect 64-73 Door hardware incomplete wires sticking out 5 \$ 5.55 East Sec 48-84 Sec 48-84 Sect 64-73 Door hardware incomplete sec 48-84 Door hardware incomplete with sec 48-84 Door hardware						1,500.00
East E4-73 Elect E4-73 Door hardware incomplete, wires sticking out 5 5 55 East E4-84 Elect A5-84 Door hardware incomplete 5 5 55 East E4-84 Elect A5-84 Door hardware incomplete 5 5 55 East E4-84 Elect B5-84 Door hardware incomplete 5 5 55 East E4-84 Elect B5-82 Elect B5-84 Door hardware incomplete 5 5 50 East E4-84 Elect Door next to Level 3 elevator has conduits and wires sticking out 5 5 1,00 East E4-92 Elect B5-92 Elec						500.00
East E-84 Elect E-8-8 Door hardware incomplete S S5					\$	500.00
East				· · · · · · · · · · · · · · · · · · ·	\$	500.00
East Elect Door next to Level 3 elevator has conduits and wires sticking out S 1,00			Elect		\$	500.00
East E2-31 Elect E3-12A junction box with wires is missing a cover plate E3 t2 2-31 Elect E3-31 telephone junction box has telephone cables spilling out of wall into the room S 50 East E2-41 Elect E2-41 telephone junction box has telephone cables spilling out of wall into the room S 50 East E2-42 Elect E2-30 Elect E2-30 telephone junction box has telephone cables spilling out of wall into the room S 50 East E2-30 Elect E2-30 telephone junction box has telephone cables spilling out of wall into the room S 50 East E2-30 Elect E2-31 deephone junction box has telephone cables spilling out of wall into the room S 50 East E2-30 Elect E2-31 deephone junction box has telephone cables spilling out of wall into the room S 50 East E2-30 Elect E2-31 deephone junction box has telephone cables spilling out of wall into the room S 50 East E2-30 Elect E2-31 deephone junction box has telephone cables spilling out of wall into the room S 50 East E2-30 Elect E2-31 deephone junction box has telephone cables spilling out of wall into the room S 50 East E2-30 Elect E2-31 deephone junction box has telephone cables spilling out of wall into the room S 50 East E2-30 Elect E2-31 deephone junction box deep selephone junction box deep selephone junction box deephone cables spilling out of wall into the room S 50 East E2-30 Elect E2-31 deephone junction box deephone cables spilling out of wall into the room S 50 East E1-31 Elect E2-31 deephone junction box deephone cables spilling out of wall into the room S 50 East E1-32 Elect E2-32 bundle of data cables hanging out of wall into the room S 50 East E1-33 Elect E2-31 deephone junction box deephone cables spilling to strain the room interest and the public publ	East		Elect		\$	1,000.00
East E2-31 Elect E2-31 telephone junction box has telephone cables spilling out of wall into the room \$ 5 50 50 50 50 50 50 50 50 50 50 50 50 5	East	E3-22	Elect	E3-22 junction box with wires is missing a cover plate	\$	100.00
East E2-42 Elect E2-42 telephone junction box has telephone cables spilling out of wall into the room \$ 5.50 East E2-30 Elect E2-30 telephone junction box has telephone cables spilling out of wall into the room \$ 5.50 East E2-30 Elect E2-30 telephone junction box has telephone cables spilling out of wall into the room \$ 5.50 East E2-31 Elect E2-31 hexposed junction box has telephone cables spilling out of wall into the room \$ 5.50 East E2-44 Elect E2-31 hexposed junction box has telephone cables spilling out of wall into the room \$ 5.50 East E2-49 Elect E2-34 elect E2-34 light swirtch over has blanks currently covered by tape. Light swirtch installed \$ 5.50 East E1-31 Elect E2-34 light swirtch cover has blanks currently covered by tape. Light swirtch not installed \$ 5.50 East E1-64 Elect E1-30 light swirtch cover has blanks currently covered by tape. Light swirtch not installed \$ 5.50 East E1-64 Elect E1-50 light swirtch cover has blanks currently covered by tape. Light swirtch not installed \$ 5.50 East E1-63 Elect E1-50 light swirtch cover has blanks currently covered by tape. Light swirtch not installed \$ 5.50 East E1-63 Elect E1-50 light swirtch cover has blanks currently covered by tape. Light swirtch not installed \$ 5.50 East E1-64 Elect E1-50 light swirtch cover has blanks currently covered by tape. Light swirtch not installed \$ 5.50 East E1-64 Elect E1-65 light swirtch cover has blanks currently covered by tape. Light swirtch not installed \$ 5.50 East E1-64 Elect E1-65 light swirtch cover has blanks currently covered by tape. Light swirtch not installed \$ 5.50 East E3-64 Elect E1-65 light swirtch cover has blanks currently covered by tape. Light swirtch not installed \$ 5.50 East E3-64 Elect E1-65 light swirtch cover has blanks currently covered by tape. Light swirtch not installed \$ 5.50 East E3-64 Elect E1-65 light swirtch cover has blanks currently covered by tape. Light swirtch not installed \$ 5.50 East E3-65 East E1-65 East E2-65 East E2-65 East E3-65 East E3-65 East E3-65 East E3-65 East E3-65 East	East	E3-12A	Elect	E3-12A junction box with wires is missing a cover plate	\$	100.00
East E2-42 Elect E2-42 telephone junction box has telephone cables spilling out of wall into the room \$ 5 50 East E2-30 Elect E2-30 telephone junction box has telephone cables spilling out of wall into the room \$ 5 50 East E2-11A Elect E2-11A exposed junction box has telephone cables spilling out of wall into the room \$ 5 50 East E2-49 Elect E2-49 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5 1,00 East E1-13 Elect E1-13 data cables sticking out of junction box \$ 5 1,00 East E1-13 Elect E1-13 data cables sticking out of junction box \$ 5 1,00 East E1-14 Elect E1-15 data cables sticking out of junction box \$ 5 25 East E1-04 Elect E1-26 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5 25 East E1-03 Elect E1-01 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5 50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5 50 East Garage Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5 50 East Garage Elect Garage has multiple open old fire alarm device junction boxes that need to be covered \$ 5 25 East Garage Elect Garage e1lect Garage has multiple open old fire alarm device junction boxes shall not be space from ceiling. Need to be covered or organized \$ 5 50 East Vaccine storage room Elect Vaccine storage room incomplete, multiple wall bin to the space from ceiling. Need to be covered or organized \$ 5 50 East Vaccine storage room Elect Vaccine storage room incomplete, multiple wall bin to the space from ceiling. Need to be covered or organized \$ 5 50 East Garage Elect Garage has multiple areas where wires spill into the space from ceiling. Need to be covered or organized \$ 5 50 East Garage Elect Vaccine storage room incomplete, multiple wall junction boxes exposed with wires. Cables spilling into space from ceiling and floors. \$ 5 50 East Garage Elect Vaccine storage room incomplet	East	E2-31	Elect	E2-31 telephone junction box has telephone cables spilling out of wall into the room	\$	500.00
East E2-30 Elect E2-30 telephone junction box has telephone cables spilling out of wall into the room \$ 5.50 East E2-11A Elect E2-11A exposed junction box needs a cover plate and 8X cables are sticking out of drywall \$ 5.50 East E2-49 Elect E2-49 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.10 East E1-32 Elect E1-13 data cables sticking out of junction box \$ 10 East E1-128 Elect E1-13 data cables sticking out of junction box \$ 2.10 East E1-130 Elect E1-13 bundle of data cables hanging out of hole in wall. Needs to be covered up \$ 5.25 East E1-04 Elect E1-04 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-04 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch n	East	E2-41	Elect	E2-41 telephone junction box has telephone cables spilling out of wall into the room	\$	500.00
East E2-11A Elect E2-11A exposed junction box needs a cover plate and BX cables are sticking out of dywall \$ \$ 5.05 East E2-49 Elect E2-49 light switch cover has blanks currently covered by tape. Light switch not installed \$ \$ 1,00 East E1-13 Elect E1-13 data cables sticking out of junction box \$ 10 East E1-28 Elect E1-28 bundle of data cables hanging out of hole in wall. Needs to be covered up \$ 2.55 East E1-04 Elect E1-104 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-01 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.50 East Stair N Elect Sair N Elect Sair N has open junction boxes along the wall that need a cover plate \$ 5.50 East Sair N Elect Sair N Blect Sair N has open junction boxes along the wall that need a cover plate \$ 5.50 East Sair N Elect Sair N Blect Sair N has open junction boxes along the wall that need a cover plate \$ 5.50 East Garage Elect Garage celling has multiple areas where wires spill into the space from celling. Need to be covered or organized \$ 5.50 East Vaccine storage room Elect Vaccine storage room incomplete, multiple wall junction boxes exposed with wires. Cables spilling into space from celling and floors. \$ 2.50 West Civil Water valve boxes asphalted over - remove asphalt from top of valve box, confirm valves are operational – clean out if required \$ 1,00 West Civil Water valve boxes asphalted over - remove asphalt from top of valve box, confirm valves are operational – clean out if required \$ 1,00 West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 1,00 West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 1,00 East Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 5.00 Main Civil Replace admanged asphalt to near the removed - 5100032. Damaged filewal	East	E2-42	Elect	E2-42 telephone junction box has telephone cables spilling out of wall into the room	\$	500.00
East E2-49 Elect E2-49 Elect E2-49 Elect E1-13 data cables sticking out of junction box S 1,00	East	E2-30	Elect	E2-30 telephone junction box has telephone cables spilling out of wall into the room	\$	500.00
East E1-38 Elect E1-38 data cables sticking out of junction box East E1-04 Elect E1-28 bundle of data cables hanging out of hole in wall. Needs to be covered up S 25 East E1-04 Elect E1-04 light switch cover has blanks currently covered by tape. Light switch not installed S 50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed S 50 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed S 50 East E1-03 Elect Stair N Blect Stair N has open junction boxes along the wall that need a cover plate East Garage Elect Garage has multiple open old fire alarm device junction boxes that need to be covered S 50 East Vaccine storage room Elect Garage lass multiple open old fire alarm device junction boxes that need to be covered or organized S 50 East Vaccine storage room Elect Vaccine storage room incomplete, multiple wall junction boxes exposed with wires. Cables spilling into space from ceiling and floors. S 50 East Vaccine storage room Elect Fintance Conduits need a weatherproof junction box cover the exposed conduits HCCC Entrance Elect Entrance conduits need a weatherproof junction box cover the exposed conduits West Civil Water valve boxes asphalted over – remove asphalt from top of valve box, confirm valves are operational – clean out if required S 1,00 West Civil Water valve boxes asphalted over – remove asphalt from top of valve box, confirm valves are operational – clean out if required S 1,00 West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear S 1,00 East Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear S 1,00 East Civil Replace sidewalk bay cut box out on in pavers East Civil Replace sidewalk (4 bays) and cut bin various areas to be replaced S 1,00 East Civil Replace damaged sidewalk (4 bays) and cut bin various areas to be replaced S 3,00 East Civil Replace damaged sidewalk at Limit of construction Civil			Elect			500.00
East E1-04 Elect E1-08 with cover has blanks currently covered by tape. Light switch not installed 5 550 East E1-04 Elect E1-04 light switch cover has blanks currently covered by tape. Light switch not installed 5 550 East E1-01 Elect E1-07 light switch cover has blanks currently covered by tape. Light switch not installed 5 550 East E1-03 Elect E1-08 light switch cover has blanks currently covered by tape. Light switch not installed 5 550 East E1-03 Elect E1-09 light switch cover has blanks currently covered by tape. Light switch not installed 5 550 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed 5 550 East E1-03 Elect 51-04 light switch not boxes along the wall that need a cover plank of the covered 5 5 550 East Stair N Elect 51-05 Garage has multiple open old fire alarm device junction boxes that need to be covered 5 5 550 East 6 Garage Elect 6 Garage ceiling has multiple average where wires spill into the space from ceiling. Need to be covered or organized 5 5 50 East 6 Vaccine storage room incomplete, multiple wall junction boxes exposed with wires. Cables spilling into space from ceiling and floors. 5 5 50 Entrance 6 Elect 6 Entrance 6 Elect 6 Entrance 6 Elect 6 Entrance 6 Elect 7 Entrance 7 Elect 7 Entrance 7 Elect 7 Entrance 7 Elect 7 Entrance 8 Elect 7 Main door entrance 8 Elect 8 Main door entrance 9 5 50 Elect 9 Entrance 8 Elect 9 Ele						1,000.00
East E1-04 Elect E1-04 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.00 East E1-03 Elect E1-01 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.00 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.00 East Stair N Elect Stair N has open junction boxes along the wall that need a cover plate \$ 25 East Garage Elect Garage has multiple open old fire alarm device junction boxes that need to be covered \$ 5.00 East Vaccine storage room Elect Garage plate area where wires spill into the space from ceiling. Need to be covered or organized \$ 5.00 East Vaccine storage room Elect Vaccine storage room incomplete, multiple wall junction boxes exposed with wires. Cables spilling into space from ceiling and floors. \$ 2,50 East Vaccine storage room Elect Vaccine storage room incomplete, multiple wall junction boxe exposed with wires. Cables spilling into space from ceiling and floors. \$ 2,50 East Vaccine storage room Elect Uacine storage room incomplete, multiple wall junction box to cover the exposed conduits \$ 2,50 East Vaccine storage room Elect Uacine storage room incomplete, multiple wall junction box to cover the exposed conduits \$ 2,50 East Civil Wain door entrance Elect Main door entrance has a data cable sticking out \$ 5 East Civil Wain valve boxes asphalted over – remove asphalt from top of valve box, confirm valves are operational – clean out if required \$ 1,00 Evest Civil Complete signage installations at front entrance West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 1,00 East Civil Replace sidewalk was where utility cut has been made through sidewalk at rear \$ 1,00 East Civil Replace valve boxes soaded over – remove sod from top of valve box, adjust box to grade, confirm valve is operational – clean out if required \$ 5.00 East Civil Replace poor restoration of asphalt on East Block mil and replace with positive drainage \$ 3,00 East Ci						100.00
East E1-01 Elect E1-01 iight switch cover has blanks currently covered by tape. Light switch not installed \$ 5.00 East E1-03 Elect E1-03 light switch cover has blanks currently covered by tape. Light switch not installed \$ 5.00 East Stair N Elect Stair N so pen junction boxes along the wall that need a cover plate \$ 5.25 East Stair N Elect Stair N has open junction boxes along the wall that need a cover plate \$ 5.00 East Garage Elect Garage has multiple open old fire alarm device junction boxes that need to be covered \$ 5.00 East Garage Elect Garage ceiling has multiple areas where wires spill into the space from ceiling. Need to be covered \$ 5.00 East Vacine storage room incomplete, multiple wall junction boxes exposed with wires. Cables spilling into space from ceiling and floors. \$ 2,50 HCCC Entrance Elect Entrance conduits need a weatherproof junction box to cover the exposed conduits \$ 10 HCCC Main door entrance Elect Main door entrance has a data cable sticking out \$ 5.00 West Civil Water valve boxes asphalted over – remove asphalt from top of valve box, confirm valves are operational – clean out if required \$ 1,00 West Civil Complete signage installations at front entrance \$ 1,00 West Civil Replace sidewalk hay where utility cut has been made through sidewalk at rear \$ 1,00 West Civil Replace sidewalk hay where sidewalk matches into unit pavers East Civil Building entry signage not completed \$ 5.00 East Civil Building entry signage not completed \$ 5.00 East Civil Replace sidewalk (4 bays) and curb in various areas to be replaced \$ 5.00 East Civil Replace poor restoration of asphalt on East Block mill and replace with positive drainage \$ 3,00 East Civil Replace poor restoration of asphalt on East Block mill and replace with positive drainage \$ 5.00 Main Civil Replace curb dramage at Landscaping Planter at Main Block Main Civil Replace dramaged sidewalk at limit of construction \$ 5.000 Main Civil Replace dramaged sidewalk at rear \$ 5.000 East Civil Replace areas palat						250.00
East Stair N Elect Stair N sopen junction boxes along the wall that need a cover plate Stair N sopen junction boxes along the wall that need a cover plate \$ 25 25 25 26 26 26 26 26 26 26 26 26 26 26 26 26						500.00
East Stair N Elect Stair N has open junction boxes along the wall that need a cover plate \$ 25 East Garage Elect Garage has multiple open old fire alarm device junction boxes that need to be covered \$ 5 So Garage Elect Garage ceiling has multiple areas where wires spill into the space from ceiling. Need to be covered or organized \$ 5 East Vaccine storage room Elect Vaccine storage room incomplete, multiple wall junction boxes exposed with wires. Cables spilling into space from ceiling and floors. \$ 2,50 HCCC Entrance Elect Entrance conduits need a weatherproof junction box to cover the exposed conduits \$ 10 HCCC Main door entrance Elect Main door entrance has a data cable sticking out \$ 5 HCCC Main door entrance Elect Main door entrance has a data cable sticking out \$ 5 HCCC West Civil Water valve boxes asphalted over — remove asphalt from top of valve box, confirm valves are operational — clean out if required \$ 1,00 West Civil Complete signage installations at front entrance \$ 1,00 West Civil Minor asphalt settlement to be milled and levelled at construction limit \$ 2,00 West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 1,00 West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 1,00 East Civil Hydrant valve boxes sodded over — remove sod from top of valve box, adjust box to grade, confirm valve is operational — clean out if required \$ 5 East Civil Building entry signage not completed \$ 5 East Civil Replace sidewalk (a bays) and curb in various areas to be replaced \$ 5 East Civil Repair water ponding area in asphalt on East Block mound chamber \$ 5 Main Civil Repair water ponding area in asphalt on East Block mound chamber \$ 5 Main Civil Repair damaged asphalt at limit of construction \$ 5 Main Civil Repair damaged asphalt at limit of construction \$ 5 Main Civil Repair damaged asphalt at limit of construction \$ 5 Main Civil Repair damaged asphalt at limit of construction \$ 5 East Civil Repair d						500.00
East Garage Elect Garage has multiple open old fire alarm device junction boxes that need to be covered \$ 500 Garage each pass multiple areas where wires spill into the space from ceiling. Need to be covered or organized \$ 500 Garage ceiling has multiple areas where wires spill into the space from ceiling. Need to be covered or organized \$ 500 Garage ceiling has multiple areas where wires spill into the space from ceiling. Need to be covered or organized \$ 500 Garage ceiling has multiple wall junction boxes exposed with wires. Cables spilling into space from ceiling and floors. \$ 2,500 Garage ceiling has multiple wall junction box to cover the exposed conduits \$ 100 Garage ceiling and floors. \$ 1,000 Garage ceiling and floors. \$ 1,000 Garage ceiling and floor entrance bas a data cable sticking out \$ 500 Garage ceiling and floor entrance bas a data cable sticking out \$ 500 Garage ceiling and floor entrance bas a data cable sticking out \$ 500 Garage ceiling and floor entrance bas a data cable sticking out \$ 500 Garage ceiling and floor entrance bas a data cable sticking out \$ 500 Garage ceiling and floor entrance bas a data cable sticking out \$ 500 Garage ceiling and floor entrance bas a data cable sticking out \$ 500 Garage ceiling and floor entrance bas a data cable sticking out \$ 500 Garage ceiling and floor entrance bas a data cable sticking out \$ 500 Garage ceiling and floor entrance bas a data cable sticking out \$ 500 Garage ceiling and floor entrance bas a data cable sticking out \$ 500 Garage ceiling and sticking out \$ 500 Garage ceiling and sticking out \$ 500 Garage ceiling and floor entrance bas a data cable sticking out \$ 500 Garage ceiling and sticking based on the sticking out \$ 500 Garage ceiling and sticking pole base to be removed \$ 500 G					<u> </u>	500.00
East Garage Elect Garage ceiling has multiple areas where wires spill into the space from ceiling. Need to be covered or organized \$ 50 East Vaccine storage room Elect Vaccine storage room incomplete, multiple wall junction boxes exposed with wires. Cables spilling into space from ceiling and floors. \$ 2,50 HCCC Entrance Elect Entrance conduits need a weatherproof junction box to cover the exposed conduits \$ 10 HCCC Main door entrance Elect Entrance conduits need a weatherproof junction box to cover the exposed conduits \$ 10 HCCC Main door entrance Elect Main door entrance has a data cable sticking out \$ 5 HCCC Main door entrance Elect Main door entrance has a data cable sticking out \$ 5 HCCC Main door entrance Elect Main door entrance has a data cable sticking out \$ 5 HCCC Main door entrance Elect Main door entrance has a data cable sticking out \$ 5 HCCC Main door entrance Elect Main door entrance has a data cable sticking out \$ 5 HCCC Main door entrance Elect Main door entrance has a data cable sticking out \$ 5 HCCC Main door entrance Elect Main door entrance has a data cable sticking out \$ 5 HCCC Main door entrance Elect Main door entrance has a data cable sticking out \$ 1,000 Hest Civil Material State of the first of the first of the first out \$ 1,000 Hest Civil Minor asphalt settlement to be milled and levelled at construction limit \$ 2,000 Hest Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 1,000 Hest Civil Replace sidewalk has where sidewalk matches into unit pavers \$ 1,000 Hest Civil Replace sidewalk has where sidewalk matches into unit pavers \$ 1,000 Hest Civil Building entry signage not completed \$ 1,000 Hest Civil Replace door entrance \$ 1,000 Hest Civil Replace goor restoration of asphalt on East Block mill and replace with positive drainage \$ 3,000 Hest Civil Replace goor resto						250.00
Fast Vaccine storage room Elect Vaccine storage room incomplete, multiple wall junction boxes exposed with wires. Cables spilling into space from ceiling and floors. \$ 2,50						500.00 500.00
HCCC Entrance Elect Entrance conduits need a weatherproof junction box to cover the exposed conduits HCCC Main door entrance Elect Main door entrance has a data cable sticking out S 5 S0 West Civil Water valve boxes asphalted over – remove asphalt from top of valve box, confirm valves are operational – clean out if required \$ 1,00 West Civil Minor asphalt settlement to be milled and levelled at construction limit \$ 2,00 West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear S 1,00 West Civil Rectify trip hazard where sidewalk matches into unit pavers East Civil Hydrant valve boxes sodded over – remove sod from top of valve box, adjust box to grade, confirm valve is operational – clean out if required S 5 East Civil Damaged sidewalk (4 bays) and curb in various areas to be replaced East Civil Damaged sidewalk (4 bays) and curb in various areas to be replaced East Civil Replace poor restoration of asphalt on East Block around chamber Main Civil Replace poor restoration of asphalt on East Block around chamber Main Civil Existing pole base to be removed - \$100032. Damaged/Spalling sidewalk at East and West Side of Front Entrance to be replaced S 3,00 Main Civil Replace curb damage at Landscaping Planter at Main Block S 5,00 Main Civil Repair asphalt settlement on main road at rear of Main Block S 5,00 Main Civil Replace damaged sidewalk at limit of construction Main Civil Replace damaged sidewalk at limit of construction Main Civil Replace damaged sidewalk at limit of construction Main Civil Replace damaged sidewalk at limit of construction Main Civil Replace damaged sidewalk at limit of construction						2,500.00
HCCC Main door entrance Elect Main door entrance has a data cable sticking out West Civil Water valve boxes asphalted over – remove asphalt from top of valve box, confirm valves are operational – clean out if required \$ 1,00 West Civil Complete signage installations at front entrance \$ 1,00 West Civil Minor asphalt settlement to be milled and levelled at construction limit \$ 2,00 West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 1,00 West Civil Rectify trip hazard where sidewalk matches into unit pavers \$ 1,00 East Civil Hydrant valve boxes sodded over – remove sod from top of valve box, adjust box to grade, confirm valve is operational – clean out if required \$ 50 East Civil Building entry signage not completed \$ 3,00 East Civil Damaged sidewalk (4 bays) and curb in various areas to be replaced \$ 3,00 East Civil Repair water ponding area in asphalt on East Block mill and replace with positive drainage \$ 3,00 East Civil Repair water ponding area in asphalt on East Block around chamber \$ 50 Main Civil Existing pole base to be removed - \$100032. Damaged/Spalling sidewalk at East and West Side of Front Entrance to be replaced \$ 10,00 Main Civil Repair damaged asphalt at limit of construction \$ 5,00 Main Civil Repair asphalt settlement on main road at rear of Main Block \$ 5,00 Main Civil Replace curb damaged sidewalk at limit of construction \$ 5,00 Main Civil Replace damaged sidewalk at limit of construction \$ 5,00 Main Civil Replace damaged sidewalk at limit of construction \$ 5,00 Main Civil Replace damaged sidewalk at limit of construction \$ 5,00 Main Civil Replace damaged sidewalk at rear \$ 5,00						100.00
West Civil Complete signage installations at front entrance \$ 1,000 West Civil Complete signage installations at front entrance \$ 1,000 West Civil Minor asphalt settlement to be milled and levelled at construction limit \$ 2,000 West Civil Minor asphalt settlement to be milled and levelled at construction limit \$ 2,000 West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 1,000 West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 1,000 West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 1,000 West Civil Replace sidewalk was where utility cut has been made through sidewalk at rear \$ 1,000 West Civil Replace sidewalk was where utility cut has been made through sidewalk at rear \$ 1,000 West Civil Replace under unde						500.00
West Civil Minor asphalt settlement to be milled and levelled at construction limit \$ 2,00 West Civil Minor asphalt settlement to be milled and levelled at construction limit \$ 2,00 West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 1,00 West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 1,00 East Civil Rectify trip hazard where sidewalk matches into unit pavers \$ 1,00 East Civil Hydrant valve boxes sodded over – remove sod from top of valve box, adjust box to grade, confirm valve is operational – clean out if required \$ 50 East Civil Building entry signage not completed \$ 3,00 East Civil Damaged sidewalk (4 bays) and curb in various areas to be replaced \$ 3,00 East Civil Replace water ponding area in asphalt on East Block mill and replace with positive drainage \$ 3,00 East Civil Replace poor restoration of asphalt on East Block around chamber \$ 50 Main Civil Asphalt padding has not been completed to eliminate ponding water. Contractor to complete remedial works on Top Course Asphalt \$ 3,00 Main Civil Existing pole base to be removed - \$100032. Damaged/Spalling sidewalk at East and West Side of Front Entrance to be replaced \$ 10,00 Main Civil Replace curb damage at Landscaping Planter at Main Block \$ 50 Main Civil Repair damaged asphalt at limit of construction \$ 2,00 Main Civil Repair damaged sidewalk at limit of construction \$ 5,00 Main Civil Replace damaged sidewalk at limit of construction \$ 5,00 Main Civil Replace damaged sidewalk at rear \$ 5,00				-		1,000.00
West Civil Minor asphalt settlement to be milled and levelled at construction limit \$ 2,000 West Civil Replace sidewalk bay where utility cut has been made through sidewalk at rear \$ 1,000 West Civil Rectify trip hazard where sidewalk matches into unit pavers \$ 1,000 West Civil Rectify trip hazard where sidewalk matches into unit pavers \$ 1,000 East Civil Hydrant valve boxes sodded over – remove sod from top of valve box, adjust box to grade, confirm valve is operational – clean out if required \$ 500 East Civil Building entry signage not completed \$ 3,000 East Civil Damaged sidewalk (4 bays) and curb in various areas to be replaced \$ 3,000 East Civil Repair water ponding area in asphalt on East Block mill and replace with positive drainage \$ 3,000 East Civil Replace poor restoration of asphalt on East Block mill and replace with positive drainage \$ 3,000 Main Civil Asphalt padding has not been completed to eliminate ponding water. Contractor to complete remedial works on Top Course Asphalt \$ 3,000 Main Civil Existing pole base to be removed - \$100032. Damaged/Spalling sidewalk at East and West Side of Front Entrance to be replaced \$ 10,000 Main Civil Replace curb damage at Landscaping Planter at Main Block \$ 500 Main Civil Repair damaged asphalt at limit of construction \$ 5,000 Main Civil Repair asphalt settlement on main road at rear of Main Block \$ 5,000 Main Civil Replace damaged sidewalk at rear						1,000.00
Replace sidewalk bay where utility cut has been made through sidewalk at rear				1 0		2,000.00
Sect Civil Rectify trip hazard where sidewalk matches into unit pavers \$ 1,000				·		1,000.00
East Civil Building entry signage not completed \$ 50 East Civil Damaged sidewalk (4 bays) and curb in various areas to be replaced \$ 3,00 East Civil Repair water ponding area in asphalt on East Block mill and replace with positive drainage \$ 3,00 East Civil Repair water ponding area in asphalt on East Block mill and replace with positive drainage \$ 3,00 East Civil Replace poor restoration of asphalt on East Block around chamber \$ 5,00 Main Civil Asphalt padding has not been completed to eliminate ponding water. Contractor to complete remedial works on Top Course Asphalt \$ 3,00 Main Civil Existing pole base to be removed - \$100032. Damaged/Spalling sidewalk at East and West Side of Front Entrance to be replaced \$ 10,00 Main Civil Replace curb damage at Landscaping Planter at Main Block \$ 5,00 Main Civil Repair damaged asphalt at limit of construction \$ 2,000 Main Civil Repair asphalt settlement on main road at rear of Main Block \$ 5,00 Main Civil Replace damaged sidewalk at rear \$ \$ 2,000						1,000.00
East Civil Building entry signage not completed East Civil Damaged sidewalk (4 bays) and curb in various areas to be replaced East Civil Repair water ponding area in asphalt on East Block mill and replace with positive drainage East Civil Repair water ponding area in asphalt on East Block mill and replace with positive drainage East Civil Replace poor restoration of asphalt on East Block around chamber S 50 Main Civil Asphalt padding has not been completed to eliminate ponding water. Contractor to complete remedial works on Top Course Asphalt S 3,00 Main Civil Existing pole base to be removed - \$100032. Damaged/Spalling sidewalk at East and West Side of Front Entrance to be replaced \$ 10,00 Main Civil Replace curb damage at Landscaping Planter at Main Block \$ 50 Main Civil Repair damaged asphalt at limit of construction \$ 2,00 Main Civil Repair asphalt settlement on main road at rear of Main Block \$ 5,00 Main Civil Replace damaged sidewalk at rear \$ 5,00				• • •		500.00
East Civil Damaged sidewalk (4 bays) and curb in various areas to be replaced East Civil Repair water ponding area in asphalt on East Block mill and replace with positive drainage East Civil Replace poor restoration of asphalt on East Block around chamber East Civil Replace poor restoration of asphalt on East Block around chamber S 500 Main Civil Asphalt padding has not been completed to eliminate ponding water. Contractor to complete remedial works on Top Course Asphalt S 3,00 Main Civil Existing pole base to be removed - \$100032. Damaged/Spalling sidewalk at East and West Side of Front Entrance to be replaced \$ 10,00 Main Civil Replace curb damage at Landscaping Planter at Main Block \$ 500 Main Civil Repair damaged asphalt at limit of construction \$ 2,000 Main Civil Repair asphalt settlement on main road at rear of Main Block \$ 5,000 Main Civil Replace damaged sidewalk at rear \$ 5,000						XXXX
East Civil Repair water ponding area in asphalt on East Block mill and replace with positive drainage \$ 3,00 East Civil Replace poor restoration of asphalt on East Block around chamber \$ 50 Main Civil Asphalt padding has not been completed to eliminate ponding water. Contractor to complete remedial works on Top Course Asphalt \$ 3,00 Main Civil Existing pole base to be removed - \$100032. Damaged/Spalling sidewalk at East and West Side of Front Entrance to be replaced \$ 10,00 Main Civil Replace curb damage at Landscaping Planter at Main Block \$ 50 Main Civil Repair damaged asphalt at limit of construction \$ 2,00 Main Civil Repair asphalt settlement on main road at rear of Main Block \$ 5,00 Main Civil Replace damaged sidewalk at rear \$ 2,00					\$	3,000.00
East Civil Replace poor restoration of asphalt on East Block around chamber \$ 50 Main Civil Asphalt padding has not been completed to eliminate ponding water. Contractor to complete remedial works on Top Course Asphalt \$ 3,00 Main Civil Existing pole base to be removed - \$100032. Damaged/Spalling sidewalk at East and West Side of Front Entrance to be replaced \$ 10,00 Main Civil Replace curb damage at Landscaping Planter at Mini Block \$ 50 Main Civil Repair damaged asphalt at limit of construction \$ 2,00 Main Civil Repair asphalt settlement on main road at rear of Main Block \$ 5,00 Main Civil Replace damaged sidewalk at rear \$ 5,000						3,000.00
Main Civil Asphalt padding has not been completed to eliminate ponding water. Contractor to complete remedial works on Top Course Asphalt \$ 3,00 Main Civil Existing pole base to be removed - \$100032. Damaged/Spalling sidewalk at East and West Side of Front Entrance to be replaced \$ 10,00 Main Civil Replace curb damage at Landscaping Planter at Main Block \$ 50 Main Civil Repair damaged asphalt at limit of construction \$ 2,00 Main Civil Repair asphalt settlement on main road at rear of Main Block \$ 5,00 Main Civil Replace damaged sidewalk at rear \$ 2,00						500.00
Main Civil Existing pole base to be removed - \$100032. Damaged/Spalling sidewalk at East and West Side of Front Entrance to be replaced \$ 10,00 Main Civil Replace curb damage at Landscaping Planter at Main Block \$ 50 Main Civil Repair damaged asphalt at limit of construction \$ 2,00 Main Civil Repair asphalt settlement on main road at rear of Main Block \$ 5,00 Main Civil Replace damaged sidewalk at rear \$ 2,00				·	\$	3,000.00
Main Civil Replace curb damage at Landscaping Planter at Main Block \$ 50 Main Civil Repair damaged asphalt at limit of construction \$ 2,00 Main Civil Repair asphalt settlement on main road at rear of Main Block \$ 5,00 Main Civil Replace damaged sidewalk at rear \$ 2,00					\$	10,000.00
Main Civil Repair asphalt settlement on main road at rear of Main Block \$ 5,00 Main Civil Replace damaged sidewalk at rear \$ 2,00					\$	500.00
Main Civil Replace damaged sidewalk at rear \$ 2,000	Main		Civil	Repair damaged asphalt at limit of construction	\$	2,000.00
					\$	5,000.00
Total \$ 84,95	Main		Civil	Replace damaged sidewalk at rear	\$	2,000.00
				Total	\$	84,950.00

\$26,850.00 M

\$22,600.00 EL

\$35,500.00 CI

STANTEC LANDSCAPE DEFICIENCIES & INCOMPLETE WORK LIST

Halton Regional Centre (HRC) - Project 2

1151 Bronte Rd, Oakville, ON

Remaining Landscape Work: Estimated Values 11/17/2023

Item	Description	Estima	ted Cost
1.0	Main Block		
1.1	On the North side of the Main Block, supply and install the Wood Screen at the Loading Dock.	ć	2 000 00
1.2		\$	2,000.00 150.00
	Supply and install (1) missing Taxus x media 'Wardii'-Ward's Yew The Tilia cordata 'Greenspire'-Greenspire Linden that is located second from the north is planted to	ې	130.00
	high. Replant in accordance with planting detail.	\$	200.00
	The five (5) Amelanchier canadensis that have been installed are under sized (50mm instead of 60mm	7	200.00
1	cal.) and are not multi-stem as specified. Remove and replace with correct variety and size. <i>New</i>		
	Recommendation: Retain the trees and request a credit for the undersized plantings.	\$	150.00
	The twelve (12) Pyrus calleryana are undersized (50mm instead of 60mm cal.). Remove and replace		
	with correct size. New Recommendation: Retain the trees and request a credit for the undersized		
	plantings.	\$	400.00
	The one (1) Quercus rubra is undersized (50mm instead of 60mm cal.). Remove and replace with		
	correct size. Observation 08/02/2023: This tree is now partially dead and unhealthy. This tree is now		
1.6	dead. Remove and Replace.	\$	800.00
1	Water is collecting along the south side of the walkway leading from the parking area to the east		
	courtyard due to the fact that the grade of the sod is above the paving and is preventing the water		
	from getting to the near-by CB. Remove a portion of the sod adjacent to the walkway and around the		
1.7	CB and lower the grade so that the sod is level with the pavement to allow for positive drainage to the	\$	1,000.00
	Cut back the extended drain pipe in the river stone swale west of the wood bridge to correct height as		
	directed by Civil Team	\$	150.00
1.9	Supply and install the wood bench on the Main Entrance sign	\$	3,000.00
	West Block	ć	C 000 00
2.1	Supply and install (3) bike racks.	\$	6,000.00
3.0	East Block		
	Remove tar marks from unit paving at the south end of the accessible parking stalls.	\$	200.00
	Remove and replace (1) dead Celtis occidentalis in the planting area between the access road and the	Ψ	200.00
	parking area	\$	700.00
	Supply and install (3) bike racks.	\$	6,000.00
	Supply and install granular base, concrete pad and bench along the sidewalk along the north façade of		,
1	the Day Care Building (excavation is complete).	\$	3,000.00
	Supply and install bench on concrete seat wall at south end of drop off zone.	\$	2,000.00
	Supply and install (2) Liriodendron tulipifera-Tulip Tree (60mm cal.) and (2) Gymnocladus dioicus-		
	Kentucky Coffee Tree (60mm cal.) along the southern edge of the existing parking lot east of the Day		
3.6	Care Building	\$	3,000.00
	Daycare Ground Level Play Area		
	Complete the detailing of the Playhouse: Circle hole windows; round chamfer of soffit facia at corners		
_	of roof; trimming of cedar shingles	\$	500.00
4.2	Supply and install decorative wood slats on existing concrete wall.	\$	4,000.00
5.0	Daycare Level 2 Play Area		
	Adjust wood boards to be flush with concrete.	\$	500.00
	Supply and install chalk board.	\$	3,000.00
5.2	expert and mean arange and ar	Y	5,000.00
6.0	General sod repair throughout site	\$	1,000.00
		-	_,
	Total	\$	37,750.00

Note: Values are estimates only and do not reflect actual costs

West Block - Schedule of Values of deficiencies & incomplete work (NOVEMBER 16 2023)

EXTERIOR

DESCRIPTION	VALUE OF DEFICIENCIES	VALUE OF INCOMPLETE WORK	TOTAL DEF+INCOMPLETE WORK
WEST BLOCK SOUTH VESTIBULE	\$100.00	\$0.00	\$100.00
WEST BLOCK SOUTH ELEVATION	\$750.00	\$5,000.00	\$5,750.00
WEST BLOCK WEST ELEVATION	\$500.00	\$1,000.00	\$1,500.00
WEST BLOCK ROOF AREA	\$200.00	\$500.00	\$700.00
TOTAL	<u>\$1,550.00</u>	<u>\$6,500.00</u>	<u>\$8,050.00</u>

INTERIOR

LEVEL 2				
ROOM NUMBER	ROOM NAME	VALUE OF DEFICIENCIES	VALUE OF INCOMPLETE WORK	TOTAL DEF+INCOMPLETE WORK
W2-01	LOBBY - WEST BLOCK	\$1,500.00		\$1,500.00
W2-01A	LOBBY - WEST BLOCK (UPPER PART)	\$3,500.00		\$3,500.00
W2-01B	SECURITY	\$2,000.00		\$2,000.00
W2-01C	RESOURCE	\$2,000.00		\$2,000.00
W2-03	LOBBY VEST - WEST BLOCK	\$1,000.00		\$1,000.00
W2-04	RAMP	\$300.00		\$300.00
W2-05	CORRIDOR (RAMP)	\$1,000.00		\$1,000.00
W2-06	WR-GN (CORRIDOR)	\$500.00		\$500.00
W2-06B	WR-GN	\$500.00		\$500.00
W2-07	WR-UNI	\$500.00		\$500.00
W2-08	WATER METERING ROOM	\$2,000.00		\$2,000.00
W2-09	REFLECTION ROOM	\$250.00		\$250.00
STD	STAIR D	\$100.00		\$100.00
TOTAL LEVEL 2		<u>\$15,150.00</u>	<u>\$0.00</u>	<u>\$15,150.00</u>

GRAND TOTALS	<u>\$16,700.00</u>	<u>\$6,500.00</u>	<u>\$23,200.00</u>
--------------	--------------------	-------------------	--------------------

NOTE:

ROOM NAMES IN RED = NOT REVIEWED

HCCC Block - Schedule of Values of deficiencies & incomplete work (NOVEMEBER 16, 2023)

EXTERIOR

DESCRIPTION	VALUE OF DEFICIENCIES	VALUE OF INCOMPLETE WORK	TOTAL DEF+INCOMPLETE WORK
NORTH ENTRANCE CANOPY	\$500.00	\$5,000.00	\$5,500.00
SOUTH ENTRANCE CANOPY	\$500.00	\$5,000.00	\$5,500.00
HCCC FENCE	\$5,000.00	\$2,000.00	\$7,000.00
BUILDING ENVELOPE	\$2,000.00	\$4,000.00	\$6,000.00
TOTAL	<u>\$8,000.00</u>	<u>\$16,000.00</u>	<u>\$24,000.00</u>

INTERIOR

LEVEL 2				
ROOM NUMBER	ROOM NAME	VALUE OF DEFICIENCIES	VALUE OF INCOMPLETE WORK	TOTAL DEF+INCOMPLETE WORK
CC2-01	INFANT 1	\$300.00		\$300.00
CC2-01A	SLEEP 1	\$400.00		\$400.00
CC2-01B	WR	\$300.00		\$300.00
CC2-07	STORAGE	\$100.00		\$100.00
STP	STAIR P	\$300.00		\$300.00
CC2-02	INFANT 2	\$300.00		\$300.00
CC2-02A	SLEEP 2	\$500.00		\$500.00
CC2-02B	WR	\$100.00		\$100.00
CC2-02C	STORAGE	\$100.00		\$100.00
CC2-03	TODDLER 1	\$1,000.00		\$1,000.00
CC2-03A	WR	\$200.00		\$200.00
CC2-03B	STORAGE	\$200.00		\$200.00
CC2-04	TODDLER 2	\$400.00		\$400.00
CC2-04A	WR	\$200.00		\$200.00
CC2-16A	FAMILY ACTIVITY AREA	\$400.00		\$400.00
CC2-05	PRE-SCHOOL 2	\$1,500.00		\$1,500.00
CC2-05A	WR	\$300.00		\$300.00
CC2-05B	STORAGE	\$100.00		\$100.00
CC2-06	PRE-SCHOOL 1	\$300.00		\$300.00
CC2-06A	WR	\$300.00		\$300.00
CC2-06B	STORAGE	\$100.00		\$100.00
CC-E1-1	ELEVATOR	\$500.00		\$500.00
STQ	STAIR Q	\$100.00		\$100.00
CC2-08	НЅКР	\$100.00		\$100.00
CC2-09A	DATA ROOM	\$100.00		\$100.00
CC2-10	LAUNDRY	\$500.00		\$500.00
CC2-12	KITCHEN	\$500.00		\$500.00
CC2-12A	PANTRY	\$100.00		\$100.00
CC2-15	OFFICE	\$500.00		\$500.00
CC2-16	ACTIVITY AREA	\$100.00		\$100.00
CC2-17	VESTIBULE	\$100.00	\$1,000.00	\$1,100.00
TOTAL LEVEL 2		\$10,000.00	<u>\$1,000.00</u>	<u>\$11,000.00</u>

LEVEL 3				
ROOM NUMBER	ROOM NAME	VALUE OF DEFICIENCIES	VALUE OF INCOMPLETE WORK	TOTAL DEF+INCOMPLETE WORK
CC03-01	MECH ROOF AREA	\$100.00	\$3,000.00	\$3,100.00
CC3-02	STORAGE	\$300.00		\$300.00
CC3-03	STAFF	\$2,300.00		\$2,300.00
CC3-03B	STORAGE	\$300.00		\$300.00
STP	STAIR P	\$500.00		\$500.00
CC3-06	CORRIDOR	\$200.00		\$200.00
CC3-06A	CORRIDOR	\$100.00		\$100.00
CC3-07	ELEVATOR ROOM	\$200.00		\$200.00
CC-E1-1	ELEVATOR	\$100.00		\$100.00
STQ	STAIR Q	\$100.00		\$100.00
CC3-08	STORAGE	\$200.00	\$2,000.00	\$2,200.00
CC3-15	INTERACTION AND GATHERING SPAC	\$300.00		\$300.00
CC3-16	ELECT ROOM	\$200.00		\$200.00
TOTAL LEVEL 3		<u>\$4,900.00</u>	<u>\$5,000.00</u>	<u>\$9,900.00</u>

GRAND TOTALS	\$22,900.00	\$22,000.00	\$44,900.00
	7==,500.00	¥==)000.00	<u> </u>

NOTE:

ROOM NAMES IN RED = NOT REVIEWED

EAST BLOCK Block - Schedule of Values of deficiencies & incomplete work (NOVEMEBER 17, 2023)

EXTERIOR	
EVIEVION	

EXTERIOR			
DESCRIPTION	VALUE OF DEFICIENCIES	VALUE OF INCOMPLETE WORK	TOTAL DEF+INCOMPLETE WORK
EAST EXTERIOR VESTIBULE AREA	\$2,000.00		\$2,000.00
EXTERIOR RAMP AREA	\$10,000.00		\$10,000.00
ROOF AREA	\$2,000.00	\$5,000.00	\$7,000.00
BUILDING ENVELOPE	\$25,000.00	\$7,500.00	\$32,500.00
TOTAL	<u>\$27,000.00</u>	<u>\$12,500.00</u>	<u>\$39,500.00</u>

ľ	V	T	Ε	R	ľ	o	

INTERIOR				
LEVEL 1				
ROOM NUMBER	ROOM NAME	VALUE OF DEFICIENCIES	VALUE OF INCOMPLETE WORK	TOTAL DEF+INCOMPLETE WORK
E1-01	COMP TRAINING LAB	\$3,500.00		\$3,500.00
E1-01A	TELEPHONE CLOSET	\$1,000.00		\$1,000.00
E1-02	WR-GN	\$1,000.00		\$1,000.00
E1-02A	WR-GN	\$2,000.00		\$2,000.00
E1-02B	WR-GN	\$100.00		\$100.00
E1-02C	WR-GN	\$100.00		\$100.00
E1-02D	WR-GN	\$100.00		\$100.00
E1-03	TRAINING ROOM 02	\$3,000.00		\$3,000.00
E1-04	TRAINING ROOM 01	\$1,000.00		\$1,000.00
E1-05A	CORRIDOR	\$1,500.00 \$1,500.00		\$1,500.00 \$1,500.00
E1-05B	CORRIDOR	* *		
E1-05C	CORRIDOR	\$500.00		\$500.00
E1-06 E1-07	STORAGE IT LAB	\$2,000.00		\$2,000.00
··	IT STORAGE			
E1-08 E1-08A	VEST	\$2,000.00		\$2,000.00
STN	STAIR N	\$1,500.00		\$1,500.00
E1-09	ELECT ROOM	\$500.00		\$500.00
E1-09 E1-10	DATA ROOM	\$500.00		\$500.00
E1-10 E1-11	FACILITIES STORAGE	\$500.00 \$1,500.00		\$500.00 \$1,500.00
E1-11 E1-11B	ELECT STORAGE	31,300.00		\$1,500.00
	ELECT			
E1-11C E1-12	HEALTH STORAGE	\$2,000.00		\$2,000.00
E1-12 E1-13	WELLNESS CENTRE 02	\$1,500.00		\$1,500.00
E1-13	HEALTH LAB (FOOD & WATER)	\$1,500.00		\$1,500.00
E1-15	WELLNESS CENTRE 01	\$1,500.00		\$1,500.00
E1-16	ORAL HEALTH STERILIZATION	\$500.00		\$500.00
E1-17	VACCINE STORAGE	\$5,000.00		\$5,000.00
E1-18	BICYCLE PARKING & STORAGE	\$250.00		\$250.00
E1-19	ELECT ROOM	\$1,500.00		\$1,500.00
E1-19A	HSKP	\$1,500.00		\$1,500.00
E1-20	FEMALE LOCKER ROOM	\$1,500.00		\$1,500.00
E1-21	WR / SHOWER FEMALE	\$1,500.00		\$1,500.00
E1-22	WR / SHOWER MALE	\$1,500.00		\$1,500.00
E1-23	MALE LOCKER ROOM	\$1,000.00		\$1,000.00
E1-23A	GN - BARRIER FREE SHOWER	\$500.00		\$500.00
E1-24	CORRIDOR	\$1,000.00		\$1,000.00
E1-26	ELEV MACHINE ROOM	\$500.00		\$500.00
E1-27	CORRIDOR	\$500.00		\$500.00
	ELEVATOR	\$250.00		\$250.00
E1-28	NEW HDF RECORDS	\$3,000.00		\$3,000.00
E1-29	HDF - RECORDS STORAGE			
E1-30	MECH. RM	\$1,000.00		\$1,000.00
E1-32	DATA CENTRE	\$1,000.00		\$1,000.00
E1-32A	VEST			
E1-34	CORRIDOR	\$500.00		\$500.00
E1-35	VEST	\$500.00		\$500.00
E1-37	MECH. RM	\$1,000.00		\$1,000.00
E1-38A	PARKING GARAGE	\$5,000.00		\$5,000.00
E1-38B	PARKING GARAGE	\$500.00		\$500.00
E1-38C	PARKING GARAGE	\$500.00		\$500.00
E1-39	GENERATOR ROOM	\$1,000.00		\$1,000.00
E1-39A	HEALTH STORAGE ROOM			\$0.00
E1-39B	UPS ROOM	\$250.00		\$250.00
E1-40	VEST	\$2,000.00		\$2,000.00
E1-41	CORRIDOR	\$250.00		\$250.00
E1-42	CORRIDOR	\$500.00		\$500.00
E1-43	SERVERY	\$350.00		\$350.00
E1-44	OH STORAGE	\$250.00		\$250.00
E1-45	нѕкр	\$1,000.00		\$1,000.00
E1-46	SHARPS STORAGE	\$100.00		\$100.00
STM	STAIR M	\$500.00		\$500.00
TOTAL LEVEL 1		<u>\$64,500.00</u>	\$0.00	<u>\$64,500.00</u>

LEVEL 2				
ROOM NUMBER	ROOM NAME	VALUE OF DEFICIENCIES	VALUE OF INCOMPLETE WORK	TOTAL DEF+INCOMPLETE WORK
E2-01	OFFICE	\$3,500.00		\$3,500.00
E2-02	OFFICE	\$750.00		\$750.00
E2-03	OFFICE	\$600.00		\$600.00
E2-04	OFFICE	\$200.00		\$200.00
E2-05	OFFICE	\$200.00		\$200.00
E2-06	OFFICE	\$500.00		\$500.00
E2-07	RESOURCE	\$100.00		\$100.00
E2-08	OFFICE	\$100.00		\$100.00
E2-09	OFFICE	\$200.00		\$200.00
E2-10	DATA ROOM	\$300.00		\$300.00
E2-10A	ELECT ROOM	\$1,000.00		\$1,000.00
E2-11	WR-MALE	\$300.00		\$300.00
E2-11A	HSKP	\$750.00		\$750.00
E2-12	WR-FEMALE	\$300.00		\$300.00
E2-13A	OFFICE SPACE	\$300.00		\$300.00
E2-13B	OFFICE SPACE	\$500.00		\$500.00
E2-13C	OFFICE SPACE	\$500.00		\$500.00
E2-13D	OFFICE SPACE	\$600.00		\$600.00
E2-13E	OFFICE SPACE	\$500.00		\$500.00
E2-14	WR-GN	\$750.00		\$750.00
E2-14A	WR-GN	\$200.00		\$200.00
E2-14B	WR-GN	\$200.00		\$200.00
E2-14C	WR-GN	\$200.00		\$200.00
E2-14D	WR-GN	\$200.00		\$200.00
E2-14E	WR-UN1	\$300.00		\$300.00
E2-15	VACCINE PICKUP ROOM			
E2-16	VACCINE DISTRIBUTION ROOM	4000 00		4000.00
	ELEVATOR	\$300.00		\$300.00
STM	STAIR M	\$2,000.00		\$2,000.00
E2-17	WORKING LOUNGE	\$2,000.00		\$2,000.00 \$200.00
E2-18 E2-19	OFFICE	\$200.00		\$200.00
E2-19 F2-20	ENCLAVE	\$200.00		*
E2-20 E2-21	OFFICE OFFICE	\$100.00 \$400.00		\$100.00 \$400.00
E2-21 E2-22	RESOURCE	\$400.00 \$200.00		\$200.00
F2-23	SECURITY ROOM	\$200.00		\$200.00
E2-23A	FACP ROOM	\$300.00		\$300.00
E2-24	HEALTH SUPPLIES DISTRIBUTION ROOM	3300.00		\$350.00
E2-25	FOOD PREMISES CONSULT	\$1,500.00		\$1,500.00
E2-26	VACCINE / ORAL HEALTH	\$2,000.00		\$2,000.00
E2-27	ENCLAVE	\$100.00		\$100.00
E2-28	ENCLAVE	\$100.00		\$100.00
E2-29	ENCLAVE	\$200.00		\$200.00
E2-30	CONSULT	\$1,500.00		\$1,500.00
E2-31	CONSULT	\$1,500.00		\$1,500.00
E2-32	MEETING / TRAINING	\$5,000.00		\$5,000.00
E2-33	RESOURCE	\$300.00		\$300.00
E2-34	SECURITY	\$300.00		\$300.00
E2-35	TEL. ROOM	\$200.00		\$200.00
E2-36	ELECT ROOM	\$200.00		\$200.00
E2-37	DATA CLOSET	\$100.00		\$100.00
E2-38	VEST	\$500.00		\$500.00
E2-39	CONSULT	\$1,500.00		\$1,500.00
E2-40	CHILDRENS ASSESSMENT ROOM	\$1,500.00		\$1,500.00
E2-40A	CHILDRENS OBSERVATION	\$500.00		\$500.00
E2-41	CONSULT	\$1,500.00		\$1,500.00
E2-42	CONSULT	\$1,500.00		\$1,500.00
E2-43	SECURED CONSULT	\$1,600.00		\$1,600.00
E2-44	LOBBY - EAST BLOCK	\$1,000.00		\$1,000.00
E2-44A	WAITING AREA	\$1,000.00		\$1,000.00
E2-45A	CORRIDOR	\$1,000.00		\$1,000.00
E2-45B	CORRIDOR	\$1,000.00		\$1,000.00
E2-46	WAITING	\$250.00		\$250.00
E2-47	TIER COUNTER	\$2,500.00		\$2,500.00
E2-48	PUBLIC RESOURCE	\$750.00		\$750.00
E2-49	MEETING	\$2,000.00		\$2,000.00
E2-49A	MEETING	\$1,500.00		\$1,500.00
E2-50	ELECT. RM	\$100.00		\$100.00

TOTAL LEVEL 2		\$59,100.0 <u>0</u>	<u>\$0.00</u>	<u>\$59,100.00</u>
STN	STAIR N	\$1,500.00		\$1,500.00
E2-56C	OFFICE	\$750.00		\$750.00
E2-56B	OFFICE	\$500.00		\$500.00
E2-56A	OFFICE	\$1,000.00		\$1,000.00
E2-55	SERVERY	\$300.00		\$300.00
E2-54	MEETING	\$1,500.00		\$1,500.00
E2-53	ENCLAVE	\$1,100.00		\$1,100.00
E2-52	VESTIBULE	\$500.00		\$500.00
E2-51	TEL. RM	\$500.00		\$500.00

LEVEL 3				
ROOM NUMBER	ROOM NAME	VALUE OF DEFICIENCIES	VALUE OF INCOMPLETE WORK	TOTAL DEF+INCOMPLETE WORK
E3-01A	OFFICE SPACE	\$500.00		\$500.00
E3-01B	OFFICE SPACE	\$750.00		\$750.00
E3-01C E3-01D	OFFICE SPACE OFFICE SPACE	\$500.00 \$500.00		\$500.00 \$500.00
E3-02	FINANCE COMM OFFICE	\$150.00		\$150.00
E3-03	OFFICE	\$1,500.00		\$1,500.00
E3-04	SAFE ROOM			\$0.00
E3-05	OFFICE	\$200.00		\$200.00
E3-06	OFFICE	\$100.00		\$100.00
E3-07	OFFICE	\$100.00		\$100.00
E3-08	OFFICE	\$100.00		\$100.00
E3-09 E3-10	ENCLAVE MEETING	\$100.00 \$200.00		\$100.00 \$200.00
E3-11	SERVERY	\$200.00		\$200.00
E3-12	WR-MALE	\$1,500.00		\$1,500.00
E3-12A	HSKP	\$100.00		\$100.00
E3-13	WR-FEMALE	\$500.00		\$500.00
E3-14	RESOURCE	\$1,100.00		\$1,100.00
E3-15	OFFICE	\$1,200.00		\$1,200.00
E3-16	OFFICE	\$200.00		\$200.00
E3-17	OFFICE	\$100.00		\$100.00
E3-18	OFFICE	\$1,100.00		\$1,100.00
E3-19 E3-20	OFFICE OFFICE	\$150.00 \$200.00		\$150.00 \$200.00
E3-21	OFFICE	\$100.00		\$100.00
E3-22	OFFICE	\$200.00		\$200.00
E3-24	DATA ROOM	\$500.00		\$500.00
E3-25A	OFFICE SPACE	\$300.00		\$300.00
E3-25B	OFFICE SPACE	\$750.00		\$750.00
E3-25C	OFFICE SPACE	\$500.00		\$500.00
E3-26	MEETING	\$1,500.00		\$1,500.00
E3-27	COMM BOARDROOM	\$500.00		\$500.00
E3-28 E3-29	OFFICE MEETING	\$500.00 \$2,500.00		\$500.00 \$2,500.00
E3-30	MEETING	\$1,300.00		\$1,300.00
E3-31	MEETING	\$1,500.00		\$1,500.00
E3-32	ENCLAVE	\$100.00		\$100.00
E3-33	ENCLAVE	\$100.00		\$100.00
E3-34	CAFE / WORKING LOUNGE	\$500.00		\$500.00
STM	STAIR M	\$500.00		\$500.00
E3-35	OFFICE	\$300.00		\$300.00
E3-36	WR-GN	\$100.00		\$100.00
E3-36A E3-36B	WR-GN WR-GN	\$500.00 \$200.00		\$500.00 \$200.00
E3-36C	WR-GN	\$1,000.00		\$1,000.00
E3-36D	WR-GN	\$200.00		\$200.00
E3-36E	WR-GN	\$200.00		\$200.00
E3-36F	WR-GN	\$200.00		\$200.00
E3-37A	OFFICE SPACE	\$500.00		\$500.00
E3-37B	OFFICE SPACE	\$200.00		\$200.00
E3-37C	OFFICE SPACE		\$2,000.00	\$2,000.00
E3-37D	OFFICE SPACE	\$1,000.00		\$1,000.00
E3-37E E3-37F	OFFICE SPACE OFFICE SPACE	\$500.00 \$200.00		\$500.00 \$200.00
E3-37G	OFFICE SPACE	\$300.00		\$300.00
E3-38	MEETING	\$1,500.00		\$1,500.00
E3-39	MEETING	\$100.00		\$100.00
E3-40	ENCLAVE	\$100.00		\$100.00
E3-41	OFFICE	\$100.00		\$100.00
E3-42	OFFICE	\$100.00		\$100.00
E3-43	OFFICE	\$300.00		\$300.00
E3-44	OFFICE	\$1,100.00		\$1,100.00
E3-45	OFFICE	\$2,100.00 \$100.00		\$2,100.00 \$100.00
E3-47 E3-48	OFFICE OFFICE	\$100.00 \$1,200.00		\$100.00 \$1,200.00
E3-50	HEALTH COMM OFFICE	\$1,200.00		\$1,200.00
E3-51	OFFICE	\$200.00		\$200.00
E3-52	OFFICE	\$1,500.00		\$1,500.00
E3-53B	CORRIDOR	\$10,000.00		\$10,000.00
E3-53C	CORRIDOR	\$7,500.00		\$7,500.00
E3-53A	JANITOR / STORAGE	\$5,000.00		\$5,000.00
E3-60	OFFICE	\$3,000.00		\$3,000.00
E3-61	OFFICE	\$1,500.00		\$1,500.00
STN STL	STAIR N STAIR L	\$1,000.00 \$100.00		\$1,000.00 \$100.00
312	ELEVATOR	\$200.00		\$200.00
	(====::-=::	,		, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
TOTAL LEVEL 3		\$65,700.00	\$2,000.00	\$67,700.00
				<u></u>
		•	+	

LEVEL 4 ROOM NUMBER	ROOM NAME	VALUE OF DEFICIENCIES	VALUE OF INCOMPLETE WORK	TOTAL DEF+INCOMPLETE WORK
E4-01A	OFFICE SPACE	\$3,000.00	JALOU OF INCOMINEUTE WORK	\$3,000.00
E4-01B	OFFICE SPACE	\$1,500.00		\$1,500.00
E4-11	HEALTH LIBRARY	\$100.00		\$100.00
4-21A	WR-GN	\$1,100.00		\$1,100.00
4-21B	WR-GN	\$700.00		\$700.00
4-21D	WR-GN	\$100.00		\$100.00
4-21E	WR-GN	\$200.00		\$200.00
4-28	OFFICE	\$1,100.00		\$1,100.00
4-29	RESOURCE	\$0.00		\$0.00
4-30	OFFICE	\$1,100.00		\$1,100.00
4-34	ENCLAVE	\$200.00		\$200.00
4-35	OFFICE	\$0.00		\$0.00
4-38	ENCLAVE	\$1,100.00		\$1,100.00
E4-39	ENCLAVE	\$1,000.00		\$1,000.00
4-40	ENCLAVE	\$1,200.00		\$1,200.00
4-41	MEETING	\$1,200.00		\$1,200.00
4-42	MEETING	\$1,200.00		\$1,200.00
E4-43	COMMISSIONERS OFFICE	\$1,500.00		\$1,500.00
4-44	OFFICE	\$1,500.00		\$1,500.00
4-45	OFFICE	\$1,500.00		\$1,500.00
4-46	RESOURCE	\$2,000.00		\$2,000.00
4-49	OFFICE	\$1,200.00		\$1,200.00
4-52	DATA RM			
4-52A	ELECT RM	\$1,500.00		\$1,500.00
4-57	OFFICE	\$200.00		\$200.00
4-58	OFFICE	\$500.00		\$500.00
4-61	ENCLAVE	\$200.00		\$200.00
4-62	ENCLAVE	\$200.00		\$200.00
4-65	ENCLAVE	\$100.00		\$100.00
4-69	OFFICE	\$1,000.00		\$1,000.00
4-70	OFFICE	\$1,200.00		\$1,200.00
4-73	MEETING	\$1,200.00		\$1,200.00
4-74	OFFICE	\$1,100.00		\$1,100.00
E4-75	OFFICE	\$1,000.00		\$1,000.00
E4-76	OFFICE	\$1,000.00		\$1,000.00
4-77	COMMISSIONERS OFFICE	\$600.00		\$600.00
E4-79	OFFICE	\$0.00		\$0.00
4-80	JANITOR	\$300.00		\$300.00
4-81	MEETING	\$1,000.00		\$1,000.00
4-82	SERVERY	\$1,000.00		\$1,000.00
4-83	WR-MALE	\$500.00		\$500.00
4-83A	HSKP	\$1,500.00		\$1,500.00
4-84	COMMISSIONERS BOARDROOM	\$1,100.00		\$1,100.00
4-85	MEETING	\$300.00		\$300.00
4-91	WR-FEMALE	\$500.00		\$500.00
4-93 (A)	OFFICE	\$750.00		\$750.00
4-93 (B)	OFFICE	\$1,500.00		\$1,500.00
4-93 (C)	OFFICE	\$500.00		\$500.00
4-95 (A)	OFFICE	\$2,000.00		\$2,000.00
4-95 (B)	OFFICE	\$1,000.00		\$1,000.00
4-95 (C)	OFFICE	\$750.00		\$750.00
4-96	OFFICE	\$500.00		\$500.00
4-97	CAFE	\$1,000.00		\$1,000.00
4-98	COMMISSIONERS BOARDROOM	\$2,000.00		\$2,000.00
4-99	MEETING	\$1,500.00		\$1,500.00
4-101	LOCKERS	\$1,000.00		\$1,000.00
4-102	LOCKERS	\$500.00		\$500.00
TOTAL LEVEL 4 \$51,500.00 \$0.00				<u>\$51,500.00</u>

GRAND TOTALS	\$267,800.00	\$14,500.00	\$282,300.00
			

Project: Haltat Regional Centre Re-development Document: Main Block Deficiency List Issue Date: November 6, 2023.



LEGEND:

= Work Completed.				
Item Name	Assigned To	Description	Photos	Work completed
MAIN BLOCK SOUTH CANOPY	Claddit	Exterior 1. MISSING TWO (2) SECTIONS OF ALUMINUM COMPOSITE CLADDING.		BUILDSKY-END OF NOV
	CEC	2. ONE OPEN ELECT. BOX AT SOFFIT.	0.1	Completed as on September 12, 2023.
	VIANA	1. MISSING NEW ROOF CAP FLASHING.		complete
	CLADDIT	2. MISSING LARGE AREA OF ALUMINUM COMPOSITE CLADDING OVER ENTRANCE DOORS.		BUILDKSY-END OF NOV
	VIANA	3. MISSING SECTIONS OF EXISTING METAL CLADDING	K	complete
MAIN BLOCK SOUTH VESTIBULE M2-01A	VIANA	4. MISSING SECTIONS OF EXISTING METAL CAP FLASHING.		complete
	BMG	5. ALUMINUM BARRIER FREE THRESHOLD IS TOO SHORT. BARRIER FREE THRESHOLD TO EXTEND THE ENTIRE WIDTH OF THE ENTRANCE DOORS AND SIDELITES.		
	VIANA	6. EXISTING METAL DOWNSPOUTS & BRACKETS TO BE RE-INSTATED AT EAST & WEST ELEVATIONS OF THE VESTIBULE.		complete
	VIANA	7. BLUESKIN WERE LEFT EXPOSED ON BOTH EAST & WEST ELEVATION OF THE VESTIBULE.		complete
	ВМС	1. REMOVE ALL STICKERS / DECALS FROM EXTERIOR GLAZING.		Complete.
	ВМС	2. MISSING CURTAINWALL CAP AT CORNER OF VESTIBULE.		Complete.

MAIN BLOCK NORTH VESTIBULE & CANOPY M2- 05	MBDA	3. BLUESKIN WERE LEFT EXPOSED ON THE NORTH ELEVATION OF THE VESTIBULE (BELOW CURTAINWALL).		MBDA 11/17/2023
	BMG	4. MISSING FLASHING ON THE NORTH ELEVATION OF THE VESTIBULE (BELOW CURTAINWALL).		
	MBDA	5. MISSING CEMENT FACED INSULATION AT EXPOSED NORTH FOUNDATION WALL (BELOW CURTAINWALL). REFER TO DETAIL 10/ A2-661		MBDA 11/17/2023
MAIN BLOCK NORTH VESTIBULE EXTERIOR RAMP AREA		No outstanding deficiencies.		Complete
	IMJ	REMOVE ALL PAINT SPLASHES FROM EXTERIOR GLAZING.		Complete
	BMG	2. MISSING FOAM IN PLACE INSULATION, SEALANT & BACKING ROD @ BOTH NEW WINDOW OPENINGS.		COMPLETE
MAIN BLOCK WEST ELEVATION	BMG	3. MISSING METAL CLOSURES @ BOTH NEW WINDOW OPENINGS.		COMPLETE
	CEC	4. OPEN ELECT. CONDUIT / PENETRATIONS AT EXISTING METAL CLADDING.		September 12, 2023
MAIN BLOCK EXTERIOR SIGNAGE	FORWARD SIGN & CEC	SIGNAGE INCOMPLETE (ELECT. CONNECTIONS INCOMPLETE).		END OF NOV
MAIN BLOCK SOUTH DRIVEWAY	SITESCAPE	OUTSTANDING ASPHALT DEFICIENCIES (WATER PONDING IN DRIVEWAY).		COMPLETE
		Interior - Level 2		
	GENERAL SPRINKLERS	1) WATER STAINS AT CEILING AROUND SPRINKLER HEADS	ಿ	Complete
	MBDA	2) MISSING ACCESS PANEL AT CEILING.		Complete
VESTIBULE M2-01A	MBDA	3) REMOVE TEMPORARY PLYWOOD COVER AT CEILING.	1	complete
	DALI DRYWALL	4) MULTIPLE AREAS OF CRACKS / DEFECTS AT GYP. BD. CEILING.	-	Complete
	MBDA	5) REMOVE TEMPORARY PLYWOOD BOXES AT BOTH EAST & WEST SIDE OF VESTIBULE.		Complete
LOBBY - MAIN BLOCK M2-01	IMJ	1) PAINT SPLASHES ON INTUMESCENT PAINT @ STEEL COLUMNS.		complete

		2) GYP. BD. & PAINT DEFECTS (AT AUDITORIUM		
	DALI and IMJ	ENTRANCE).		complete
	DALI and IMJ	3) GYP. BD. & PAINT DEFECTS (AT LIGHT COVE – AUDITORIUM ENTRANCE).		complete
	CEC	4) DISPLACED LIGHT DIFFUSER IN RECESSED LIGHT.		Completed as on September 12, 2023.
	CHUBB	1) OPEN ELECT. BOX.	Ī,	MBDA EOW
	WILLSENS	2) SEALANT AT TIER 1 CABINET MILLWORK CRACKING.	and the	complete
	WILLSENS	3) GAPS AT FRONT OF TIER 1 DESK TO BE INFILLED WITH WHITE SEALANT.		complete
TIER1 COUNTER M2-02	SANDS	4) MISSING BASE AT BACK OF TIER 1 DESK.		August 21, 2023
	EGRESS	5) MISSING DOOR HARDWARE ON DOOR M2-02.		complete
	DALI	1) GYP. BD. CRACKS & PAINT DEFECTS.		complete
CORRIDOR M2-04 (OUTSIDE SECURITY M2-03)	CHUBB	2) OPEN ELECT. BOXES.	:/	MBDA EOW
GEOGRAFI M2-03)	СНИВВ	3) MISSING ADO's OUTSIDE DOORS M2-27B & M2-27C.		ADO'S INSTALLED.RFI SUBMITTED FOR PB LOCATIONS
	MBDA	1) LARGE GAP AT FLOOR GRILLES (TRIP HAZARD).		11/17/2023
	BMG	2) GAP IN FLOOR FINISH AT EXTERIOR DOOR THRESHOLDS (TRIP HAZARD).		complete
VESTIBULE M2-05	IMJ	3) MULTIPLE GYP. BD. & PAINT DEFECTS / WATER STAINS ON WALL CEILINGS, COLUMNSETC		MBDA 11/17/2023
	EGRESS	4) DOORS M2-05 & M2-05B DO NOT OPEN FULLY (90 DEG) WHEN ADO'S ARE USED.		11/10/2023
ACCESS HALTON M2-06	EGRESS	DEFECTS AT WOOD DOOR EDGE @ DOOR M2-06	77	COMPELTE

CAFE M2-07	EGRESS	1) MISSING DOOR HARDWARE AT CLOSET DOORS M2- 26 & M2-26A.		complete
	MBDA	2) DAMAGED CEILING TILES.		complete
WR-UNI M2-14	MBDA	1) REMOVE ALL TEMPORARY SIGNAGE.		complete
	MBDA	1) REMOVE ALL TEMPORARY SIGNAGE (OUTSIDE STAIR J).		
CORRIDOR M2-15	IMJ	2) GYP. BD. & PAINT DEFECTS (OUTSIDE ROOMS M2- 12A & M2-12K).		complete
	DALI	3) CRACKS IN GYP. BD. CEILING (OUTSIDE STAIR J)		complete
	DALI	1) CRACKS IN GYP. BD. (OUTSIDE ROOM M2-44)		complete
CORRIDOR M2-16	DALI	2) CRACKS IN GYP. BD. CEILING (OUTSIDE ROOM M2-21)		
SOLUTION TO	MBDA	3) REMOVE ALL TEMPORARY SIGNAGE (OUTSIDE DOOR M2-16).	District Co.	complete
	IMJ	4) PAINT & GYP. BD. DEFECTS AT DOOR M2-16.		complete complete
ASSET MANAGEMENT	IMJ	1) PAINT DEFECTS AT DOOR M2-17.		complete
STORAGE M2-17	CHUBB	2) CARD READER MISSING AT DOOR M2-17.	, 8	complete
MEETING M2-18	СНИВВ	1) CARD READER MSSING AT DOOR M2-18.		Complete
	MBDA	2) DISPLACED CEILING TILES.		Complete
MEETING M2-19	CHUBB	1) CARD READER MSSING AT DOOR M2-19.		Complete
	MBDA	2) DISPLACED CEILING TILES.	4	Complete
MEETING M2-20	СНИВВ	1) CARD READER MSSING AT DOOR M2-20.		Complete
	MBDA	2) DISPLACED CEILING TILES.	42	Complete

MEETING M2-21	СНИВВ	1) CARD READER MISSING AT DOOR M2-21.	Complete
JANITOR M2-25	IMJ	PAINT DEFECTS AT DOOR.	Complete
	MBDA	1) REMOVE ALL TEMPORARY SIGNAGE.	Complete
WR-GN M2-12F	CEC	2) LIGHT FIXTURE NOT WORKING.	September 12, 2023
AUDITORIUM M2-27	BMG, EGRESS & CHUBB	1) DOORS M2-27A ARE INCOMPLETE. MISSING FIRE RATED GLASS MISSING HARDWARE MISSING CARD READERS MISSING ADO'S	Complete
	СНИВВ	2) OPEN ELECT. BOXES AT ENTRANCE DOORS M2-27A	Complete
STORAGE M2-30	MBDA	1) GYP. BD. DEFECTS ABOVE DOORS M2-30 & M2-30B.	11/17/2023
OTOTOTOL M2-50	СНИВВ	2) OPEN ELECT. BOXES AT DOORS M2-30 & M2-30B.	COMPLETE
SERVERY M2-32	EGRESS	1) MISSING HARDWARE AT DOORS M2-32D.	Complete
	EGRESS	2) DOORS M2-32D DO NOT CLOSE PROPERLY.	
SHIPPING / RECEIVING M2-	ALLOY FUSION	1) MISSING NEW STEEL STAIR AT EXTERIOR DOCK AREA.	Complete
41	ALLOY FUSION & MBDA	2) TEMPORARY STAIR & GUARDS STILL IN PLACE AT EXTERIOR DOCK.	COMPLETE
STAIR STJ	MBDA	1) REMOVE DEBRIS ALL TEMPORARY SIGNAGE.	Complete
		Interior Level 2	
		Interior - Level 3	
	IMJ	1) PAINT DEFECT AT DOOR STJ3.	Complete
			Complete

STAIR STJ	MBDA	2) REMOVE DEBRIS & ALL TEMPORARY SIGNAGE.		Complete
	SANDS	3) MISSING FLOOR FINISH & NOSINGS ON TREADS GOING UP.		
	MBDA	4) GENERAL CLEANUP REQUIRED.		August 21, 2023 Complete
	EGRESS	1) DOOR DEFECT AT DOOR M3-01.	0	Door to be changed to wood door. Closed.
	СНИВВ	2) MISSING CARD READER AT DOOR M3-01.		annulate
	MBDA	3) GENERAL CLEANUP REUIRED.		Complete
MEETING M3-01	SANDS	4) EXPOSED GYP. BD. @ BASE OF PC350 (BOTH SIDES). PROVIDE BLACK RESILIENT BASE AS REQ'D.		August 21, 2023
	IMJ	5) PAINT SPLASHES ON NORTH FACING GLAZING.		Complete
	IMJ	6) PAINT DEFECTS ON NORTH FACING WINDOW.		Complete
	MBDA	7) DISPLACED CEILING TILES.		Complete
	EGRESS	1) DOOR DEFECT AT DOOR M3-02.	®	Door to be changed to wood door.
	CHUBB	2) MISSING CARD READER AT DOOR M3-02.		Complete
	MBDA	3) GENERAL CLEANUP REUIRED.		Complete
MEETING M3-02	SANDS	4) EXPOSED GYP. BD. @ BASE OF PC350 (BOTH SIDES). PROVIDE BLACK RESILIENT BASE AS REQ'D.		August 21, 2023
	MBDA	5) DISPLACED CEILING TILES.		Complete
	MBDA	6) DAMAGED GYP. BD. @ CORNER.		Complete

MEETING M3-03	СНИВВ	MISSING CARD READER AT DOOR M3-03.	COMPLETE
MEETING M3-04	СНИВВ	MISSING CARD READER AT DOOR M3-04.	COMPLETE
MEETING M3-05 CHUBB MISSING CARD READER AT DOOR M3-05.		Complete	
		1) REMOVE ALL TEMPORARY SIGNAGE AT STAIR J.	
	MBDA		Complete
	DALI and IMJ	2) GYP. BD. & PAINT DEFECTS (OUTSIDE JANITOR M3-09).	Complete
	IMJ	3) SEVERAL AREAS OF GYP. BD. & PAINT DEFECTS @ CEILING (OUTSIDE MEETING M3-11).	Complete
CORRIDOR M3-07	BMG	4) POOR GLASS ALIGNMENT AT GLASS GUARD (AT LEAST 4 – 5 GLASS PANELS WITH APPROX. 6MM MISALIGNMENT).	INI REVIEW
	WILLSENS	5) SHARP CORNERS AT WOOD GUARD (SAFETY HAZARD).	Complete
	IMJ	6) PAINT DEFECTS AT ALL WALL SCONCES.	Complete
	IMJ	7) PAINT SPLASHES ON RECESSED CEILING LIGHTS.	Complete
	EGRESS	1) DOORS M3-11A & M3-11B ARE INCOMPLETE.	Complete
MEETING M3-11	BMG	2) 1 HR. FIRE RATED SEPARATIONS AT DOORS M3-11A & M3-11B ARE INCOMPLETE.	COMPETE
		3) ROOM M3-11 NOT READY FOR REVIEW / OCCUPANCY.	Complete

HRC PROJECT 2 - LIST OF ALL OUTSTANDING CO'S - PCO'S - CD'S - CCN'S - CLAIMS (DEC 21, 2023)

CO's	DESCRIPTION	\$ VALUE	STATUS	COMMENTS
517	CCN 442 PCO519 CD95 Elect CCN E106 CaTech	\$650.74	MBDA SIGNED	HRC TO APPROVE
565	CCN 466 PCO585R1 CCN340 Vaccine Room Drywall	\$39,160.00	MBDA SIGNED	HRC TO APPROVE
566	CCN 467 PCO607R1 West Block Infill - Basement Level	\$9,360.00	MBDA SIGNED	HRC TO APPROVE
567	CCN 468 PCO625 Cladding CD81 Struct CCN S45	\$16,565.00	MBDA SIGNED	HRC TO APPROVE
568	CD 128 ELECT CCN E140	\$2,389.17	MBDA SIGNED	HRC TO APPROVE
569	CD 129 ELECT CCN E141	\$369.84	MBDA SIGNED	HRC TO APPROVE
570	CCN 469 PCO 636 Connect BAS Controller in Vaccine Room	\$646.10	ISSUED TO MBDA	MBDA TO SIGN
571	CCN 400 EAST BLOCK STACK STRUCT CCNS50	\$31,751.87	ISSUED TO MBDA	MBDA TO SIGN
572	CCN470 PCO124 SI66 East Block Windows	\$4,320.00	NOT ISSUED	WAITING FOR HRC APPROVAL
573	CCN446 DOOR SHOE RETROFIT	\$49,337.22	ISSUED TO MBDA	MBDA TO SIGN
574	CCN473 PCO616 West Block and East Block Display Cases	\$7,737.60	NOT ISSUED	WAITING FOR HRC APPROVAL
575	CD124 ELECT CCN E133	\$5,783.84	NOT ISSUED	WAITING FOR HRC APPROVAL
576	CD130 ELECT CCN E142	\$2,545.17	NOT ISSUED	WAITING FOR HRC APPROVAL
TOTAL		<u>\$170,616.55</u>		

CD's	DESCRIPTION	\$ VALUE	STATUS	COMMENTS
40	EAST BLOCK LEVEL 1 REVISIONS (RFI 309)	\$14,619.56	REVISED QUOTE PROVIDED	STANTEC TO REVIEW
91	WEST BLOCK HANDRAIL SUPPORT (RFI #687)		NO QUOTE PROVIDED	MBDA TO PROVIDE QUOTE
111	ELECT CCN E125 (RFI #738)		NO QUOTE PROVIDED	MBDA TO PROVIDE QUOTE
131	MECH CCN M89 (HCCC HOSE BIB)		NO QUOTE PROVIDED	MBDA TO PROVIDE QUOTE
<u>TOTAL</u>		<u>\$14,619.56</u>		

CCN's	DESCRIPTION	\$ VALUE	STATUS	COMMENTS
2	ARBORIST REPORT REVISIONS		NO QUOTATION	CCN TO BE CANCELLED
6	REVISED MECH VALVE TAGS (RFI26-MECH CCN M3)		NO QUOTATION	MBDA TO PROVIDE QUOTE
13R1	STRUCT CCN 3 (RFI 80)		NO QUOTATION	MBDA TO PROVIDE QUOTE
83	ADD PLAM 5		NO QUOTATION	CCN TO BE CANCELLED
109	REV KITCHEN COUNTER AT SINKS (SD 196)		NOT ISSUED	NO ACTION
118	MECH CCNM30 (RFI 297-298)		NOT ISSUED	NO ACTION
173	EAST BLOCK L1 SLAB IN E1-07 (RFI #194)		NOT ISSUED	NO ACTION
188	PCO 223R2 SI90 Door Schedule Clarifications		NOT ISSUED	STANTEC TO REVIEW HRC COMMENTS
209	EAST BLOCK DAMPERS (CCN165-CCN M54R3)		NO QUOTATION	MBDA TO PROVIDE QUOTE
234	STUD REINF FOR TV'S (EAST BLOCK L3)		NOT ISSUED	NO ACTION
325R1	REVISE FRIDGE SPECS (RFI #222)		NO QUOTATION	MBDA TO PROVIDE QUOTE
350	EAST BLOCK ROOM E2-23 CEILING UPDATE		NO QUOTATION	MBDA TO PROVIDE QUOTE
398	ELECT CCN E108		NO QUOTATION	MBDA TO PROVIDE QUOTE
428	PCO561 Changes to Re-program Elevators		NOT ISSUED	STANTEC TO REVIEW HRC COMMENTS
471	ELECT CCN E143		NO QUOTATION	MBDA TO PROVIDE QUOTE
472	ELECT CCN E144		NOT ISSUED	WAITING FOR HRC APPROVAL
TOTAL		<u>\$0.00</u>	·	·

PCO's	DESCRIPTION	\$ VALUE	STATUS	COMMENTS
159	Corian Countertops from PLAM	\$18,863.80	STANTEC REVIEWED ONCE	PCO TO BE RETRACTED
163	Additional Rebar for Level 3 East Block	\$10,937.15	STANTEC REVIEWED ONCE	PCO TO BE RETRACTED
200	Floor Flattening	\$370,831.00	PCO REJECTED	PCO TO BE RETRACTED
223R1	SI #90 Door Schedule Clarifications	\$8,762.87	STANTEC REVIEWED ONCE	MBDA TO REVISE PCO
422R1	Door Frame Installation	\$33,442.00	STANTEC REVIEWED TWICE	MBDA TO REVISE PCO
471R1	CD #36 - Part 2 - East Block Curtainwall	\$210,046.26	STANTEC REVIEWED TWICE	MBDA TO REVISE PCO
517	Main Block Level 3	\$6,510.60	STANTEC REVIEWED TWICE	MBDA TO REVISE PCO
582	CCN #362R1 - CD #86 - East Block Stair M - Drywall	\$294,638.40	STANTEC REVIEWED 3 TIMES	MBDA TO REVISE PCO
637	West Block Glass Guard	\$5,255.25	PCO REJECTED	MBDA TO REVIEW
TOTAL		\$558,655.3 <u>8</u>		