November 10, 2021

95 St. Clair Avenue West Suite 1500 Toronto, Ontario Canada M4V 1N6

T 416.961.4111 F 416.961.3176 www.wzmh.com

WZMH ARCHITECTS

Baycrest Project and Construction Management 23 Railside Rd. North York, ON 3MA 1B2

Attention: Mr. Daniel Mombourquette

Re: 3500 Steeles Avenue East – Atrium East Entrance Vestibule

Project No. 06641.020

Substantial Performance Form 9

Dear Daniel,

We are pleased to submit herewith the Construction Act Form 9 dated November 10, 2021, acknowledging Substantial Performance achieved on October 18, 2021 for the above noted project. Publishing this document in print (example Daily Commercial News), or electronic format, is the sole responsibility of Baycrest. WZMH and the Owner, 3500 Steeles Avenue East LP, require confirmation, that the Form 9 has been published according to the Construction Act.

Please contact the undersigned if you have any queries regarding the above.

Yours truly,

WZMH ARCHITECTS

Ted DuArte

Lic. Tech. OAA, MRAIC, LEED® Green Associate WZMH Architects

Attach.

Form 9 and Baycrest Calculations

cc. Greg Moore – Quantum Project Management Services Inc. Gary Jackson – Canderel

> Marianne Patterson - Canderel Harrison Chan – WZMH Hady Lotfy – WZMH

Len Abelman, OAA, MRAIC
Mohammed Al-Atheri, OAA, MRAIC
Supreet Barhay, OAA, MRAIC, LEED AP BD+C
Carl Blanchaer, OAA, FRAIC
Nicola Casciato, OAA, MRAIC
Harrison Chan, OAA, MRAIC
Jee-Young Kang, B.Arch
Jeffrey Leong-Poi, OAA, MRAIC
David Moore, OAA, FRAIC, LEED AP
Richard Myers, OAA, MRAIC, LEED AP BD+C
Moran Olsha, B.Tech, LEED AP
Zenon Radewych, B. Tech
Robert Sampson, OAA, MRAIC
John White OAA, MRAIC

Chief Financial Officer Henry Ng CPA, CA

Principals

FORM 9 CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

Construction Act

City of Ma	arkham					
		(County/District/Regional Municipa	lity/Town/City in which premises are situated)			
3500 Stee	eles Ave	East, Markham, Ontario, L3	R 0X1			
	(5	street address and city, town, etc., or, if the	ere is no street address, the location of the premises)			
This is to ce	ertify that	the contract for the following impro	vement:			
3500 Stee	eles - At	rium East Entrance Vestibule				
		(short descri	ption of the improvement)			
to the above	e premise	es was substantially performed on	ned on October 18, 2021 (date substantially performed) (owner and contractor, where there is no payment certifier) East LP st, Markham, Ontario, L3R 0X1			
	(short description of the improvement) ove premises was substantially performed on October 18, 2021 (date substantially performed) (payment certifier where there is one) (owner and contractor, where there is no payment certifier) owner: 3500 Steeles Avenue East LP for service: 3500 Steeles Ave East, Markham, Ontario, L3R 0X1 Baycrest Construction & Project Management for service: 23 Railside Rd. Unit #5 & #6					
Date certific	cate signe	ed: November 10, 2021				
	the above premises was substantially performed on October 18, 2021 (date substantially performed) (payment certifier where there is one) (payment certifier where there is one) (payment certifier where there is one) (owner and contractor, where there is no payment certifier) me of owner: 3500 Steeles Avenue East LP dress for service: Baycrest Construction & Project Management dress for service: 23 Railside Rd. Unit #5 & #6 me of payment certifier (where applicable): WZHM Architects					
	(1)	,	(c			
Name of ow	vner:	3500 Steeles Avenue East L	P			
Address for	service:	3500 Steeles Ave East, Mark	kham, Ontario, L3R 0X1			
Address for service		Baycrest Construction & Pro	ject Management			
Address for service:		23 Railside Rd. Unit #5 & #6				
⊠ A.		tion of premises for preservation of teeles Ave East, Markham, C				
			ne premises, a legal description of the premises, lentifier numbers and addresses for the premises)			
□ B.	Office to	which claim for lien must be given t	to preserve lien:			
	(if the lier	n does not attach to the premises, the nam	ne and address of the person or body to whom the claim for lien must be given)			

Ted DuArte

From: Daniel Mombourquette <dmombourquette@baycrestgc.com>

Sent: October 18, 2021 9:04 AM

To: Ted DuArte
Cc: Hady Lotfy

Subject: [EXTERNAL] 3500 Steeles Ave East - East Entrance Vestibule Renovations - Substantial

Completion

Attachments: DEF List.pdf; OAA-OGCA_Document100 - 3500 Steeles Ave E..pdf

Follow Up Flag: Follow up Flag Status: Flagged

Good Day Ted,

Hope all is well,

Sorry forgot to send this to you, please see attached OAA Document, the updated deficiency list and the 3, 2, 1 formula below. Based on this formula we are now substantially complete on our end.

Regarding the 3-2-1 calculation please see my calculation below:						
Contract Total:	%	\$	889,126.00			
3% of first \$1,000,000.00:	3%	\$	26,673.78			
2% of next \$1,000,000.00:	2%	\$	-			
1% of balance:	1%	\$	-			
Total:		S	26,673.78			
Remaining Billing:						
Contract & Changes:		\$	6,370.00			
Remaining Deficiency Value:		S	1,750.00			
Total:		\$	8,120.00			

Please let me know if there is anything else required in order to obtain the signed form 9 for publication.

Thank you,





23 Railside Rd., Unit #5 & #6 Toronto, Ontario, M3A 1B2

Office: 416.444.0200 Ext. 2236 | Fax: 416.444.3496 | Cell: 416.993.9204 Email: dmombourquette@baycrestgc.com | Web: www.baycrestgc.com



RE: Deficiency List

Dated: October 18th

Contractor: Baycrest Project & Construction Management

Owner: Canderal Management Inc.

Project Name: East Entrance Vestibule

Location: 3500 Steeles Ave East, Markham, On

Baycrest to provide quote to lift 8 columns up to 3mm away from ceiling and put collar at the base. Will make it look not an after thought Item #3 Steel Angles Baycrest G.C Steel angles have to be sanded down and painted with the BASF paint. Item #4 Roof Baycrest G.C Since the membrane has been installed to close to the edge and is noticeable, Baycrest will have the roofers onsite to back and re-torch the roof. If not acceptable then a stainless steel angle around the roof. Item #5 Stainless Steel Baseboards Baycrest G.C Completed and closed Expansion Joint Cover Baycrest G.C Completed and closed Comple		ns	ACTION BY	STATUS	
Item #2	m #1	Flooring	Baycrest G.C	Open	
Baycrest to provide quote to lift 8 columns up to 3mm away from ceiling and put collar at the base. Will make it look not an after thought Item #3 Steel Angles Baycrest G.C Steel angles have to be sanded down and painted with the BASF paint. Item #4 Roof Baycrest G.C Since the membrane has been installed to close to the edge and is noticeable, Baycrest will have the roofers onsite to back and re-torch the roof. If not acceptable then a stainless steel angle around the roof. Item #5 Stainless Steel Baseboards Baycrest G.C Completed and closed Item #6 Expansion Joint Cover Baycrest G.C Completed and closed Item #7 Weatherstripping on Sliding Doors Baycrest G.C Completed and closed Completed and closed Item #7 Weatherstripping on Sliding Doors Baycrest G.C Completed and closed Completed and closed Item #7 Weatherstripping on Sliding Doors Baycrest G.C Completed and closed Completed and closed Item #7 Weatherstripping on Sliding Doors Baycrest G.C Completed and closed Completed and closed Item #8 Completed and closed Item #9 Weatherstripping on Sliding Doors Item #1 Weatherstripping on Sliding Doors Item #2 Weatherstripping on Sliding Doors Item #1 Weatherstripping on Sliding Doors Item #1 Weatherstripping on Sliding Doors Item #2 Weatherstripping on Sliding Doors Item #3 Weatherstripping on Sliding Doors Item #4 Weatherstripping on Slid	pansion join	t, hose shoe need to be repaired. Work to be complete within the next	15 days		
Item #3 Steel Angles Baycrest G.C Steel angles have to be sanded down and painted with the BASF paint. Item #4 Roof Baycrest G.C Since the membrane has been installed to close to the edge and is noticeable, Baycrest will have the roofers onsite to back and re-torch the roof. If not acceptable then a stainless steel angle around the roof. Item #5 Stainless Steel Baseboards Baycrest G.C Completed and closed	m #2	Exterior Columns	Baycrest G.C	Closed	
Steel angles have to be sanded down and painted with the BASF paint. Steel angles have to be sanded down and painted with the BASF paint. Steel angles have to be sanded down and painted with the BASF paint. Steel angles have to be sanded down and painted with the BASF paint. Steel Baycrest G.C Staince the membrane has been installed to close to the edge and is noticeable, Baycrest will have the roofers onsite to back and re-torch the roof. If not acceptable then a stainless steel angle around the roof. Stainless Steel Baseboards Baycrest G.C Completed and closed Steem #6 Expansion Joint Cover Completed and closed Steem #7 Weatherstripping on Sliding Doors Baycrest G.C Completed and closed	ycrest to pro	ovide quote to lift 8 columns up to 3mm away from ceiling and put colla	r at the base. Will make	e it look like its	
Steel angles have to be sanded down and painted with the BASF paint. tem #4 Roof Baycrest G.C Since the membrane has been installed to close to the edge and is noticeable, Baycrest will have the roofers onsite to back and re-torch the roof. If not acceptable then a stainless steel angle around the roof. tem #5 Stainless Steel Baseboards Baycrest G.C Completed and closed tem #6 Expansion Joint Cover Baycrest G.C Completed and closed tem #7 Weatherstripping on Sliding Doors Baycrest G.C Completed and closed	t an after th	ought			
Roof Since the membrane has been installed to close to the edge and is noticeable, Baycrest will have the roofers onsite to back and re-torch the roof. If not acceptable then a stainless steel angle around the roof. Stainless Steel Baseboards Completed and closed Rem #6 Expansion Joint Cover Baycrest G.C Completed and closed Rem #7 Weatherstripping on Sliding Doors Completed and closed	m #3	Steel Angles	Baycrest G.C	Closed	
Since the membrane has been installed to close to the edge and is noticeable, Baycrest will have the roofers onsite to back and re-torch the roof. If not acceptable then a stainless steel angle around the roof. Stainless Steel Baseboards Baycrest G.C	el angles ha	ave to be sanded down and painted with the BASF paint.			
back and re-torch the roof. If not acceptable then a stainless steel angle around the roof. Stainless Steel Baseboards Baycrest G.C	m #4	Roof	Baycrest G.C	Closed	
Item #5 Stainless Steel Baseboards Baycrest G.C Completed and closed Item #6 Expansion Joint Cover Baycrest G.C Completed and closed Item #7 Weatherstripping on Sliding Doors Completed and closed	ce the mem	brane has been installed to close to the edge and is noticeable, Baycres	t will have the roofers	onsite to cut	
Completed and closed Item #6	ck and re-to	rch the roof. If not acceptable then a stainless steel angle around the ro	of.		
Item #6	m #5	Stainless Steel Baseboards	Baycrest G.C	Closed	
Completed and closed Item #7 Weatherstripping on Sliding Doors Baycrest G.C Completed and closed	mpleted and	d closed			
Item #7 Weatherstripping on Sliding Doors Baycrest G.C Completed and closed	m #6	Expansion Joint Cover	Baycrest G.C	Closed	
Completed and closed	mpleted and	d closed			
	m #7	Weatherstripping on Sliding Doors	Baycrest G.C	Closed	
Item #8 Small Leak Baycrest G.C	mpleted and	d closed			
	m #8	Small Leak	Baycrest G.C	Open	
Small leak at the west side of the sliding door, this was caulked over the weekend but	all leak at th	he west side of the sliding door, this was caulked over the weekend but			
watching to ensure the leak has been fixed	tching to en	sure the leak has been fixed			