

This is to certify that Contract # 2024-2026 for the following:

Replacement/Rehabilitation of 5 Non-Structural Culverts at Hwy: 401, 404, 7

was substantially performed on: 19 Dec, 2024

Recommended by: *Glen Warner*
Contract Administrator

14 February 2025
Date Recommended

Approved by: *Manijio Auguma*
(payment certifier) Area Manager Construction

20 February 2025
Date Certified

Ministry of Transportation, 159 Sir William Hearst Ave, Downsview, ON, M3M 0B7
Address

Toronto, Durham, York Region
County/District/Regional Municipality/Town/City in which the Work is located

20m South of Highway 7 and Coronation Road Intersection, Highway 401 and Nortonville Road Interchange (E-N/S Ramp), Highway 401 and Meadowvale Road Interchange (N/S-E Ramp), 2.7km east of Highway 401 and Bloor Street Intersection, Highway 404 and Major Mackenzie Drive Interchange (E-N Ramp) as described in the executed contract

Name of Owner: His Majesty The King in Right of Ontario as represented by the Minister of Transportation

Address for Service: Ministry of Transportation
159 Sir William Hearst Avenue
Downsview, Ontario
M3M 0B7

Name of Contractor: Dufferin Construction Company

Address for Service: 585 Michigan Drive, Unit 1 Oakville, ON L6L 0G1

Office to which claim for lien must be given to preserve lien:

**Ministry of Transportation of Ontario
Director, Legal Services Branch
125 Sir William Hearst Avenue, 1st Floor
Downsview, Ontario
M3M 0B5**

This notice published in the *Daily Commercial News* **as declared by the Contractor on PH-CC-817**

Distribution: 1) Contractor, 2) Contract Administrator (file), 3) Team Lead, Contract Tendering – Contract Management Office, St. Catharines, 4) Construction Management Office