

115 Sandford Fleming Drive, Suite 200 Collingwood, Ontario L9Y 5A6

tathameng.com

Certificate of Substantial Performance

File	Cont	tract	Contract No.	
112168	We	II #2 and Treatment System Upgrades	112168-21	
Date	Cont	tractor	Owner	
July 13, 2021	H20	Ontario Inc.	Parkbridge Lifestyle Communities Inc.	
	Des	escription of Works		
	100 rem pip elec	pply and installation of a new pump, piping and pitless adapter in Well #2; 450 m of 0 mm Ø DR17 HDPE watermain from Well #2 into the existing treatment room; process movals and modifications in the treatment room including two magnetic flow meters, oing valves and appurtenances; an exterior well pump control panel at Well #2; and ectrical, instrumentation and control equipment, all for the Huron Haven/The Bluffs at uron Well #2 and Treatment System Upgrades.		
	Not	Notification		
	1.	Tatham Engineering Limited certifies the contract for the above noted improvements was substantially performed on:	July 13, 2021	
	2.	Identification of premise for preservation of liens:	Part of Lot 3, West of Lake Road Concession, in the Western Division	

Part of Lot 3, West of Lake Road Concession, in the Western Division of the former Township of Colborne and Lot 3, Broken Front Concession, in the Western Division of the former Township of Colborne, all of which is designated at Part 1 on reference Plan 22R-2238, in the Township of Ashfield-Colborne-Wawanosh, County of Huron

Owner

3. The Office to which claim for lien and affidavit must be given to preserve lien:

Contact

Owner	Contractor	Certifier
Parkbridge Lifestyle Communities Inc.	H2Ontario Inc.	Tatham Engineering Limited
70 Huron Street Collingwood, Ontario L9Y 4L4	71 Webster St, Unit A New Hamburg, Ontario N3A 1W8	115 Sandford Fleming Drive, Collingwood, Ontario L9Y 5A6
Approval	PH	
Rod Langford		July 13, 2021
Signing Authority	Signature	Date

I:\2012 Projects\112168 - Huron Haven Village\112168-21 - Well 2\Construction\Substantial Performance Certificate\Huron Haven Well #2 Upgrades - Certificate of Substantial Performance - 112168-21.docx