



Rutherford Contracting Ltd.

224 Earl Stewart Drive
Aurora, ON L4G 6V7

T: 905 726 4888
F: 905 726 4889

TRANSMITTAL

Colliers Project Leaders
15255 Orbitor Drive, Suite 101
Mississauga, Ontario
L4W 5M6
SBS Modified Bitumen - 1967 Repair
RCL PROJECT #21041

Date: Nov 04, 2021

From: Hunter Jackson
Direct Dial: (416) 270 – 1490

To: **Daily Commercial News**
500 Hood Road, 4th Floor
Markham, ON L3R 9Z3

Phone: (905) 752 - 5408
Fax: (800) 947 - 7966

Attn: **Advertising Department**

Re: **Publication of Certificate of Substantial Performance**

Forwarded by:

☐ mail ☒ email
☐ courier ☐ hand delivered

For your:

☐ info ☐ review/approval
☒ action ☐ file

Please find attached the following documentation for the above-mentioned project:

- Certificate of Substantial Performance – 1 Page

Please publish as soon as possible.

Best Regards,

Hunter Jackson,
Rutherford Contracting Ltd.

FORM 9
CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE
CONTRACT UNDER SECTION 32 OF THE ACT

Construction Act

Midland, Ontario

(County/District/Regional Municipality/Town/City in which premises are situated)

Ste. Marie Among the Hurons, 16164 Highway 12 East, Midland, Ontario, L4R 5E3

(street address and city, town, etc., or, if there is no street address, the location of the premises)

This is to certify that the contract for the following improvement:

1072733-272506 - SBS Modified Bitumen - 1967 Repair

(short description of the improvement)

to the above premises was substantially performed on 2021-10-13

(date substantially performed)

Date certificate signed: 2021-10-28

Carter Shieck

Digitally signed by Carter Shieck
DN: C=CA, E=cshieck@boldengineering.ca, O=Bold
Engineering, CN=Carter Shieck
Date: 2021.10.28 15:51:12-04'00'

(payment certifier where there is one - signature required)

(owner and contractor, where there is no payment certifier -
signatures required)

Name of owner: COLLIERS PROJECT LEADERS

Address for service: 5255 Orbitor Drive, Suite 101, Mississauga, Ontario L4W 5M6

Name of contractor: Rutherford Contracting LTD.

Address for service: 224 Earl Stewart Drive

Name of payment certifier (where applicable): Bold Engineering

Address: 2778 Dufferin Street, Suite 104, Toronto, ON, M6B 3R7

(Use A or B, whichever is appropriate)

☒ A. Identification of premises for preservation of liens:

Ste. Marie Among the Hurons, 16164 Highway 12 East, Midland Ontario, L4R 5E3

(if a lien attaches to the premises, a legal description of the premises,
including all property identifier numbers and addresses for the premises)

☐ B. Office to which claim for lien must be given to preserve lien:

(if the lien does not attach to the premises, the name and address of the person or body to whom the claim for lien must be given)