

## Certificate of Substantial Performance Request

<b>To:</b>	Daily Commercial News	<b>From:</b>	Annie Jelic
<b>Email:</b>	dcncertificates@cmdgroup.com	<b>Date:</b>	December 9 2022
<b>Phone:</b> <b>Fax:</b>	(905) 752-5516 (800) 947-7966	<b>Project</b>	1171 Pioneer Rd Bldg Envelope Upgrades Stracor # 22-2583 Client # N22030673

<b>Description of Improvement</b>	<b>Address of Improvement</b>	<b>Date of Substantial Performance</b>
Bldg Envelope Upgrades Stracor # 22-2583 Client # N22030673	1171 Pioneer Rd	December 7, 2022

**Comments:**

Please publish the above mentioned project. If you have any questions, please contact the sender at the number given below.

Thank you,

Annie Jelic  
Attached: Certificate of Substantial Performance

**FORM 9**  
**CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE**  
**CONTRACT UNDER SECTION 32 OF THE ACT**

*Construction Act*

Burlington

(County/District/Regional Municipality/Town/City in which premises are situated)

1171 Pioneer Road Burlington ON L7M 1A7

(street address and city, town, etc., or, if there is no street address, the location of the premises)

This is to certify that the contract for the following improvement:

Building Envelope Repairs

Stracor # 22-2583 Client # N22030673

(short description of the improvement)

to the above premises was substantially performed on December 07, 2022

(date substantially performed)

Date certificate signed: December 08, 2022

Aravind Gopi

(payment certifier where there is one)

(owner and contractor, where there is no payment certifier)

Name of owner: Bell Canada

Address for service: 100 Wynford Drive, North York, ON M3C 4B4

Name of contractor: Stracor Inc.

Address for service: 2170 Speers Rd., Unit #2, Oakville ON L6L 2X8

Name of payment certifier (where applicable): BRES

Address: 100 Wynford Drive, North York, ON M3C 4B4

(Use A or B, whichever is appropriate)

☐ A. Identification of premises for preservation of liens:

(if a lien attaches to the premises, a legal description of the premises,  
including all property identifier numbers and addresses for the premises)

☒ B. Office to which claim for lien must be given to preserve lien:

President and CEO of Bell Canada, 100 Wynford Drive, North York, ON M3C 4B4

(if the lien does not attach to the premises, a concise description of the premises, including addresses,  
and the name and address of the person or body to whom the claim for lien must be given)