

May 8, 2023

375 University Ave., Suite 901 Toronto, ON M5G 2J5 b: 416-599-LINK (5465) www.engineeringlink.ca

22-0055-00

Trinity Custom Masonry Limited 74 Mack Avenue Scarborough, ON M1L 1M9

Attention: Sean Fee

Re: Duke of Connaught JSPS, 70 Woodfield Road, Toronto ON Basement Cluster Column Repair – West Elevation Substantial Performance

Dear Sean:

Please find enclosed the Certificate of Substantial Performance for the above noted project. Please provide the following information prior to submitting the release of holdback:

- 1. Proof of publication in the Daily Commercial News;
- 2. All warranty papers for the work;
- 3. Maintenance Manuals
- 4. As-built Drawings
- 5. WSIB Clearance Certificate; and
- 6. Statutory Declaration for the release of holdback.

We trust this is the information you require at this time. Should you have any questions or concerns please do not hesitate to contact me.

Regards, Engineering Link Incorporated

Mushur Amakur

Per: Michael Anders, B.Eng., EIT Building Envelope EIT b: 416-599-5465 x181 c: 647-701-6686 e: Michael.A@englink.ca

Encl. Certificate of Substantial Performance and Substantial Completion Financial Statement

To: Sean Fee Cc: Bill May sean.fee@tcmltd.ca william.may@tdsb.on.ca

H:\2022\0001 - 0399\22-0055 - 70 Woodfield Rd., Toronto - Duke of Connaught JSPS\Contract_Admin\substantial performance & close out\22-0055_Certificate of Substantial Performance_2023-05-08.docx

City of Toronto		
(County/District/Regional Municipality/Town/City in which premises are situated)		
70 Woodfield Road, Toronto ON, M4L 2W6		
(Street address and city, town, etc. or, if there is no street address, the location of the premises)		
This is to certify that the contract for the following improvement:		
Basement Cluster Column Repair – West Elevation		
(Short Description of the Improvement)		
To the above premises was substantially performed on:		May 3, 2023
		(Date Substantially Performed)
Date Certificate Signed: May 8, 2023		
Mutuel Amphier		
month of power		
(Payment Certifier Where There is One)		(Owner and Contractor, Where There is No Payment Certifier)
Name of Owner: Toronto District School Board		strict School Board
Address for Service:	5050 Yonge Street, 3 rd Floor, Toronto, Ontario, M2N 5N8	
Name of Contractor:	Trinity Custom Masonry Limited	
Address for Service:	74 Mack Avenue, Scarborough, ON M1L 1M9	
Address for service.		
Name of Payment Certifier (where applicable):	Engineering Link Incorporated	
Address:	375 Univer	sity Avenue, Suite 901, Toronto, Ontario, M5G 2J5
(Use A or B, whichever is appropriate)		
A. Identification of premises for preservation of liens:		
(If a lien attaches to the premises, a legal description of the premises, including all property identifier numbers and addresses for the premises))		
B. Office to which claim for lien must be given to preserve lien:		

15 Oakburn Crescent, Toronto, ON, M2N 2T5

(If the lien does not attach to the premises, the name and address of the person or body to whom the claim for lien must be given)