

Tel: (905) 949-5050 Fax: (289) 805-4216

Email: <u>info@rdgengineering.com</u>
Web: <u>www.rdgengineering.com</u>

FORM 9 CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

Construction Lien Act

City of Toronto

(County/District/Regional Municipality/Town/City in which premises are situated)

169 Fort York Boulevard, Toronto, Ontario, (M5V 0C8)

(Street address and city, town, etc., or, if there is no street address, the location of the premises)

This is to certify that the contract for the following improvement:

Parking Garage Waterproofing Repairs

(short description of the improvement)

To the above premises was substantially performed on: June 19, 2024

(date substantially performed)

Date certificate signed: <u>June 24, 2024</u> <u>RDQ Engineering Inc.</u>

(payment certifier where there is one)

Rudin Qordja, M.Sc., P.Eng.

Name of Owner: <u>Toronto Standard Condominium Corporation No. 2307</u>

Address for Service: 169 Fort York Boulevard, Toronto, Ontario, (M5V 0C8)

Name of Contractor: Moderno Restoration Inc.

Address for Service: 2220 Midland Avenue, Unit 15, Toronto, Ontario, (M1P 3E6)

Name of Payment Certifier: <u>RDQ Engineering Inc.</u>

(where applicable)

Address for Service: 2399 Cawthra Road, Unit 201, Mississauga, Ontario, (L5A 2W9)

(*Use A or B whichever is appropriate*)





Tel: (905) 949-5050 Fax: (289) 805-4216

Email: <u>info@rdqengineering.com</u> Web: <u>www.rdqengineering.com</u>

A. Identification of premises for preservation of liens:

TSCC No. 2307; 169 Fort York Boulevard, Toronto, Ontario, (M5V 0C8)

(where liens attach to premises, reference to lot and plan or instrument registration number)

B. Office to which claim for lien and affidavit must be given to preserve lien:

Icon Property Management Inc.; 365 Evans Avenue, Toronto, Ontario, (M8Z 1K2)

(where liens do not attach to premises) R.R.O. 1990, Reg. 175, Form 9