

August 07, 2024

Mr. Kirk Gillespie, B. A. Podium Restoration Ltd. Unit 6 – 448 Gibraltar Drive Mississauga, ON L5T 2N8

Via e-mail: kirk@podiumrestoration.com

Re: Substantial Performance – Repairs to Underground Tunnel Structure and Mechanical Room at 300 Steeles Avenue East, Thornhill, ON

Dear Mr. Gillespie,

Attached is the Certificate of Substantial Performance for the above subject project. Please submit the following documents with your holdback draw:

- Certificate of Publication;
- 2. Letter of Warranty for work performed indicating the warranty period as being two (2) years for the date of Substantial Performance of the Work.
- 3. Statutory Declaration Certificate;
- 4. WSIB Certificate; and
- 5. Contractor Contact Information for Warranty Purposes.

CERTIFICATE OF SUBSTANTIAL COMPLETION

(Form 6 of the Construction Lien Act)

Toronto, Ontario

(County/District or Regional Municipality/City or Municipality in which premises are situated)

300 Steeles Avenue East, Thornhill, ON

(Street address and city, town etc. or if there is no street address, the location of the premises)

This is to certify that the contract for the following improvement:

Repairs to Underground Tunnel Structure and Mechanical Room At Bayview Glen Alliance Church – 300 Steeles Avenue East, Thornhill, ON

(short description of the improvement)

to the above premises was

substantially performed on: July 30, 2024

(date substantially performed)

Date certificate signed:

August 07, 2024

(signature of payment certified where there is one)

Name of owner: The Board of Directors

Bayview Glen Church

Address for service: 300 Steeles Avenue East

Thornhill, ON L3T 1A7

Name of contractor: Podium Restoration Ltd.

(signatures of owner and contractor, where there is no

payment certifier)

Address for service: Unit 6 – 448 Gibraltar Drive

Mississauga, ON L5T 2N8

Name of payment certifier: Gillespie Building Consultants Limited

(where applicable)

Address: 156-3085 Kingston Road

Scarborough, Ontario, M1M 1P1

(Use A or B whichever is appropriate)

A: Identification of premises for preservation of liens:

Bayview Glen Alliance Church 300 Steeles Avenue East Thornhill, Ontario

(where liens attach to premises, reference to lot and plan or instrument registration number)

B: Office to which claim for lien and affidavit must be given to preserve lien: