

September 3, 2024

23-0369-00

Cordeiro Roofing Ltd.
88 Horner Avenue,
Toronto, ON M8Z 5Y3

Attention: Kevin Goncalo

Re: Emery Collegiate Institute
3395 Weston Road, North York, ON M9M 2V9
Partial Roof Replacement – Roof Areas A5, B3, D1, D2, E2, E7, F3, FG1, FG2, G2, G5, H
Substantial Performance Letter

Dear Kevin:

Please find enclosed the Certificate of Substantial Performance (Form 9) for the above-mentioned project. Please provide the following information prior to submitting the release of holdback:

1. Proof of publication in the Daily Commercial News;
2. All warranty papers for the work;
3. Maintenance Manuals
4. As-built Drawings;
5. WSIB Clearance Certificate; and,
6. Statutory Declaration for the release of holdback.

We trust this is the information you require at this time. Should you have any questions or concerns please do not hesitate to contact me.

Regards,
Engineering Link Incorporated

V. Maleev

Per: Vladimir Maleev, M.Eng., P.Eng., BSS
Partner
b: 416-599-5465 x164
c: 416-272-7350
e: Vladimir.m@englink.ca

Encl. Certificate of Substantial Performance Form 9

To: Kevin Goncalo kevin@cordeiroroofing.com
Cc: Ron Olanday ron.olanday@tdsb.on.ca

H:\2023\0001 - 0599\23-0369 - 3395 Weston Rd-Emery CI\Contract_Admin\substantial performance & close out\23-0369-00 - Emery CI - Substantial Performance Certificate.docx

FORM 9
CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE
CONTRACT UNDER SECTION 32 OF THE ACT

Construction Act

City of Toronto

(County/District/Regional Municipality/Town/City in which premises are situated)

EMERY COLLEGIATE INSTITUTE – 3395 Weston Road, North York, ON M9M 2V9

(street address and city, town, etc., or, if there is no street address, the location of the premises)

This is to certify that the contract for the following improvement:

Partial Roof Replacement - Roof Areas A5, B3, D1, D2, E2, E7, F3, FG1, FG2, G2, G5, and H

(short description of the improvement)

to the above premises was substantially performed on **August 23, 2024**

(date substantially performed)

Date certificate signed: **September 03, 2024**

V. Maleev

(payment certifier where there is one)

(owner and contractor, where there is no payment certifier)

Name of owner: **Toronto District School Board**

Address for service: **15 Oakburn Crescent, Toronto, ON M2N 2T5**

Name of contractor: **Cordeiro Roofing Ltd.**

Address for service: **88 Horner Avenue, Toronto, ON M8Z 5Y3**

Name of payment certifier (where applicable): **Engineering Link Incorporated**

Address: **375 University Avenue, Suite 901, Toronto, ON M5G 2J5**

(Use A or B, whichever is appropriate)

☐ A. Identification of premises for preservation of liens:

(if a lien attaches to the premises, a legal description of the premises,
including all property identifier numbers and addresses for the premises)

☒ B. Office to which claim for lien must be given to preserve lien:

15 Oakburn Crescent, Toronto, ON M2N 2T5

(if the lien does not attach to the premises, a concise description of the premises, including addresses,
and the name and address of the person or body to whom the claim for lien must be given)