Construction Act

R.S.O. 1990, Chapter C.30 Last Amendment: 2018, C.17, Sched. 8, S.1-20

CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

TORONTO, ONTARIO

77 CARLTON STREET TORONTO, ONTARIO

This is to certify that the Contract for the following improvement:

to the above premises was substantially performed on JUNE 11, 2024

PARKING GARAGE AND PODIUM DECK REHABILITATION

Date certificate signed: JUNE 14, 2024

(Payment Certifier)

Name of Owner: METRO TORONTO CONDOMINIUM CORPORATION NO.

619 C/O DEL PROPERTY MANAGEMENT

Address of Service: 77 Carlton Street

Toronto, ON M5B 2J7

Name of Contractor: **COMPLETE CONCRETE RESTORATION LTD.**

Address for Service: 9782 Castlederg Sideroad

Caledon, Ontario L7E 0S3

Name of Payment Certifier: **READ JONES CHRISTOFFERSEN LTD.**

Address: 100 University Avenue, North Tower, Suite 400

Toronto, ON, M5J 1V6

A. Identification of premises for preservation of liens:

77 CARLTON STREET TORONTO, ON M5B 2J7