

April 4, 2025

23-0047-02

375 University Ave., Suite 901

Toronto, ON M5G 2J5 b: 416-599-LINK (5465)

www.engineeringlink.ca

Brook Restoration Ltd. 11 Kelfield Street Etobicoke, ON M9W 5A1

Attention: Sidra Ansari

Re: York University - 4700 Keele Street, Toronto

Service Tunnel Crack and Leak Repair - Phase 1

Substantial Performance

Dear Sidra:

Please find enclosed the Certificate of Substantial Performance for the above noted project. Please provide the following information prior to submitting the release of holdback:

- 1. Proof of publication in the Daily Commercial News;
- 2. All warranty papers for the work;
- 3. As-built Drawings
- 4. WSIB Clearance Certificate; and
- 5. Statutory Declaration for the release of holdback.

We trust this is the information you require at this time. Should you have any questions or concerns please do not hesitate to contact me.

Regards,

Engineering Link Incorporated

Per: Deirdre Vickers, P.Eng., B.A.Sc.

).V:ckm

Associate

c: 647-542-7885

e: deirdre.v@englink.ca

Encl. Certificate of Substantial Performance and Substantial Completion Financial Statement

sansari@brookrestoration.ca To: Sidra Ansari

Cc: Inessa Chapira ichapira@yorku.ca

H:\2023\0001 - 0599\23-0047 - 4700 Keele St_Service Tunnel Leaks\23-0047-00 & 23-0047-02 (Phase 1)\Contract_Admin\substantial performance & close out\23-0047-02_Substantial Performance

City of Toronto		
(County/District/Regional Municipality/Town/City in which premises are situated)		
4700 Keele Street, Toronto, ON M3J 1P3		
(Street address and city, town, etc. or, if there is no street address, the location of the premises)		
This is the second of the state		
This is to certify that the contract for the following improvement:		
Service tunnel concrete and interior waterproofing repairs		
(Short Description of the Improvement)		
To the above promises was substantially performed on:		Fabruary 20, 2025
To the above premises was substantially performed on:		February 28, 2025 (Date Substantially Performed)
		(Bate Gastantially Fortellinea)
Date Certificate Signed: April 4, 2025		
D. J. ckin		
/		
(Payment Certifier Where There is One) (Owner and Contractor, Where There is No Payment Certifier)		
Name of Owner:	York Univers	ity
	AZOO Kaala Chasat Taranta ON MOLADO	
Address for Service:	4700 Keele Street, Toronto, ON M3J 1P3	
Name of Contractor: Brook Restor		ration Ltd.
Address for Service:	11 Kelfield S	treet, Etobicoke, ON M9W 5A1
Name of Payment Certifier (where applicable): Engineering		Link Incorporated
Address:	375 Universi	ty Ave., Suite 901, Toronto, ON, M5G 2J5
	373 011170131	ty /wc., June 301, 10101110, 514, 14130 233
Use A or B, whichever is appropriate)		
A. Identification of premises for preservation of liens:		
4700 Keele Street, Toronto, Ont. M3J 1P3		
(If a lien attaches to the premises, a legal description of the premises,		
including all property identifier numbers and addresses for the premises))		
R Office to which claim for lien must be given to preserve lien:		
B. Office to which claim for lien must be given to preserve lien:		