



vallee

*Consulting Engineers,
Architects & Planners*

CERTIFICATE OF SUBSTANTIAL PERFORMANCE

HALDIMAND COUNTY, ONTARIO

(District, Region, or City in which premises are situated)

YORK ROAD, COUNTY ROAD 9, 0.02KM WEST OF HALDIMAND HIGHWAY 54

(Street address and city or town)

This is to certify that the contract for the following (Short description of improvement)

YORK BRIDGE BARRIER REPAIR

was substantially performed on	FRIDAY, OCTOBER 22, 2021
Date certificate signed	WEDNESDAY, NOVEMBER 3, 2021
Payment Certifier	G. DOUGLAS VALLEE LIMITED
Address	2 TALBOT STREET NORTH, SIMCOE, ON, N3Y 3W4
Name of Owner	THE CORPORATION OF HALDIMAND COUNTY
Address for service	53 THORBURN ST., CAYUGA, ON, N0A 1E0
Name of Contractor	LANDFORM CIVIL INFRASTRUCTURE INC.
Address for service	75 CASCADE ST., HAMILTON ON, L8E 3B7

- A. Identification of premises for preservation of liens (where liens attach to premises)
- B. Office to which claim for lien and affidavit must be given (where liens do not attach to premises)
**HALDIMAND COUNTY,
53 THORBURN ST.
CAYUGA, ONTARIO
N0A 1E0**

Braden Ongena, B.A.Sc., E.I.T.
G. DOUGLAS VALLEE LIMITED
Consulting Engineers, Architects & Planners

H:\Projects\2021\21-091 York Bridge Barrier Damages\Contract Admin\Substantial Performance\Certificate of Substantial Performance.docx