Form 9

## **Construction Act**

## CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

Toronto

(Country/Distract/Regional Municipality/Town/City or Borough of Municipality of Metropolitan Toronto in which the Premises are situated)

	209 & 215 Fort York	
This is to certify that the contr		
	Driveway & Waterp	roofing Repairs
	(short description of th	e improvement)
to the above premises was substantially performed on		October 27, 2021 (date substantially performed)
Date Certificate Signed:	23-Nov-21	
San	Jun	
(payment ent	ifier where there is one)	(owner and contractor, where there is no payment certifier)
Name of owner	Toronto Standard Condo	minium Corporation No. 2181
Address for service	c/o Crossbridge Condominium Services Ltd. 209 & 215 Fort York Blvd. Toronto, ON,	
Name of Contractor	Roma Building Restoration Ltd.	
Address for service	20 Cadetta Rd. Brampton, ON_L6P 0X4	
Name of payment certifier	Edison Engineers Inc.	
Address	17 Ogilvie St. Dundas, ON_L(H 2S1	
(Use A or B whichever is appropriate	e)	

 A. Identification of premises for preservation of liens: 76181 being all of PINs: 21418-137/140/217/224

(Where liens attach to premises, reference to lot and plan or instrument registration number)

□ B. Office to which claim for lien and affidavit must be given to preserve lien: