

FORM 9
CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE
CONTRACT UNDER SECTION 32 OF THE ACT

Construction Act

Township of Mulmur

(County/District/Regional Municipality/Town/City in which premises are situated)

3rd Line East Culvert is located on 3rd Line East between Side Road 30 and Mulmur Nottawasaga Townline in Mulmur, Ontario (44°16'27.9"N 80°06'51.5"W)

(street address and city, town, etc., or, if there is no street address, the location of the premises)

This is to certify that the contract for the following improvement:


3rd Line E Emergency Culvert Replacement

(short description of the improvement)

to the above premises was substantially performed on **December 3, 2021**

(date substantially performed)

Date certificate signed: **December 7, 2021**



(payment certifier where there is one)

(owner and contractor, where there is no payment certifier)

Name of owner: **Township of Mulmur**

Address for service: **758070 2 Line E, Mulmur, ON L9V 0G8**

Name of contractor: **Drexler Construction Limited**

Address for service: **5274 Wellington 27, Guelph/Eramosa, ON N0B 2K0**

R.J. Burnside & Associates

Name of payment certifier (where applicable): **Limited**

Address: **15 Townline, Orangeville, Ontario L9W 3R4**

(Use A or B, whichever is appropriate)

☐ A. Identification of premises for preservation of liens:

(if a lien attaches to the premises, a legal description of the premises,
including all property identifier numbers and addresses for the premises)

☒ B. Office to which claim for lien must be given to preserve lien:

758070 2 Line E, Mulmur, ON L9V 0G8

(if the lien does not attach to the premises, the name and address of the person or body to whom the claim for lien must be given)