## patersongroup

consulting engineers

## CERTIFICATE OF SUBSTANTIAL PERFORMANCE

## OF THE CONTRACT UNDER SECTION 32 OF THE CONSTRUCTION LIEN ACT

154 Colonnade Road South Ottawa, Ontario Canada K2E 7J5 Tel: (613) 226-7381 Fax: (613) 226-6344

> Building Science Geotechnical Engineering Environmental Engineering Hydrogeology Geological Engineering Materials Testing

www.patersongroup.ca

1.	City of Ottawa	
	(County, District or Regional Municipality, City or Borough)	
2.	71 Somerset Street West, Ottawa ON	
	(Street address and city, town etc., or, if there is no street address, the location of the premises)	
3.	This is to certify that the contract for the following improvement:	
	Phase 1 (Mock-Up at Unit 301)	- Window & Patio Door Replacement at CCC No.74
		(short description of the improvement)
To the above premises was		tantially performed on: June 23, 2019, (balance of contract work)
4.	Name of owner:	Carleton Condominium Corporation No.74
	Address for service:	% Condominium Management Group
		434 Queen Street
		Ottawa, Ontario, K1R 7V7
5.	Name of contractor:	Lor-Issa Construction Inc.
		3140 Carp Road
		Carp, Ontario, K0A 1L0
6.	Name of payment certifier:	Paterson Group Inc.
		9 Auriga Drive
		Ottawa, Ontario, K2E 7T9
7.	Identification of premises for preservation of liens:  Carleton Condominium Corporation No.74	
		71 Somerset Street West
		Ottawa, Ontario, K2P 2G2
8.	Recommended by consultant:	Date: June 27, 2022
		Christopher Lyons, A.Sc.T.

Ottawa North Bay