FORM 9 CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

Construction Act

| Toronto |
|---|
| (County/District/Regional Municipality/Town/City in which premises are situated) |
| Maintenance Building #22B, Centre Island, Toronto, Ontario (Street address and city, town, etc., or, if there is no street address, the location of the premises) |
| This is to certify that the contract for the following improvement: |
| Roof Replacement and Repair for the Utility Building 22B Centre Island |
| (Short description of the improvement) |
| to the above premises was substantially performed on June 23, 2022 (Date substantially performed) |
| Date certificate signed: July 5, 2022 |
| (Payment certifier where there is one) (Owner and contractor, where there is no payment certifier) |
| Name of owner: City of Toronto Address for service: 55 John Street, 14th Floor, Toronto, ON M5V 3C6 |
| Name of contractor: Brook Restoration Ltd. |
| Address for service: 11 Kelfield Street, Etobicoke, Ontario, M9W 5A1 |
| Name of payment certifier (where applicable): Remy Consulting Engineers Ltd. |
| Address: _75 Westmore Dr., Toronto, Ontario, M9V 3Y6 |
| (Use A or B, whichever is appropriate) |
| |
| Maintenance Building #22B, Centre Island, Toronto, Ontario (If a lien attaches to the premises, a legal description of the premises, including all property identifier numbers and addresses for the premises) |
| ☐ B. Office to which claim for lien must be given to preserve lien: |
| (If the lien does not attach to the premises, the name and address of the person or body to whom the claim for lien must be given) |