## Construction Act

R.S.O. 1990, Chapter C.30 Last Amendment: 2018, C.17, Sched. 8, S.1-20

## CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

## 190 SIMCOE STREET PETERBOROUGH, ONTARIO K9H 2H7

This is to certify that the Contract for the following improvement:

## 2021 PARKING GARAGE AND CULVERT REHABILITATION

Date certificate signed: JULY 27, 2022

(Payment Certifier)

Name of Owner: CITY OF PETERBOROUGH

Address of Service: 500 George Street North

Peterborough, ON K9H 3R9

Name of Contractor: **BROOK RESTORATION LTD.** 

Address for Service: 11 Kelfield Street

Etobicoke, ON M9W 5A1

Name of Payment Certifier: **READ JONES CHRISTOFFERSEN LTD.** 

Address: 100 University Avenue, North Tower, Suite 400

Toronto, ON, M5J 1V6

A. Identification of premises for preservation of liens:

190 SIMCOE STREET, PETERBOROUGH, ONTARIO K9H 2H7