Form 9

Construction Act

CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

Richmond Hill, Ontario

(Country/Distract/Regional Municipality/Town/City or Borough of Municipality of Metropolitan Toronto in which the Premises are situated)		
11 Plaisance Rd., Richmond Hill (Street Address and city, town, or if there is no street address, the location of the premises)		
This is to certify that the contract for	or the following improvement:	
Balcony Replacement Phase I (short description of the improvement)		
	(short description of the imp	vovemenų
to the above premises was substantially performed on		June 30, 2022 (date substantially performed)
Date Certificate Signed:	August 3, 2022	
San		
payment of titler	where there is one)	(owner and contractor, where there is no payment certifier)
Name of owner	York Condominium Corpora	tion No. 238
Address for service	c/o Malvern Condominium F 205 - 9140 Leslie Street Richmond Hill, ON, L4B0A9	Property Management
Name of Contractor	Brook Restoration Ltd.	
Address for service	11 Kelfield St. Toronto , ON,	
Name of payment certifier	Edison Engineers Inc.	
Address	105 - 6 Shields Court Markham, ON, L3R 4S1	
	for preservation of liens: /ork composed of the whole o	f Block O

 \square B. Office to which claim for lien and affidavit must be given to preserve lien:

(Where liens do not attach to premises)