

CERTIFICATE OF SUBSTANTIAL PERFORMANCE

OF THE CONTRACT UNDER SECTION 32 OF THE CONSTRUCTION LIEN ACT

9 Auriga Drive Ottawa, Ontario Canada K2E 7T9 Tel: (613) 226-7381

Geotechnical Engineering Environmental Engineering Hydrogeology Materials Testing Building Science Rural Development Design Retaining Wall Design Noise and Vibration Studies

patersongroup.ca

(Street address and city, town etc., or, if there	e is no street address, the location of the	premises)
This is to certify that the contract	et for the following improveme	ent:
Asphalt Shingle Roof Replace	ement	
	(short description of the improv	ement)
To the above premises was sub	estantially performed on:	August 25, 2022
Name of owner:	Carleton Condominium	Corporation No. CCC 513
Address for service:	c/o Jane Wilson, Property Manager, CMG	
	424 O Ct. Ottown	Ontario K1P V7
	434 Queen St., Ottawa,	Olitario, Kin Vi
	434 Queen St., Ottawa,	Olitario, KTH V7
Name of contractor:	SML Construction	Ontaile, KIN V7
Name of contractor:		
Name of contractor:	SML Construction	t D
Name of contractor: Name of payment certifier:	SML Construction 663 Notre Dame St. Uni	t D
	SML Construction 663 Notre Dame St. Uni Embrun, Ontario, K0A 1	t D
	SML Construction 663 Notre Dame St. Uni Embrun, Ontario, KOA 1	t D
	SML Construction 663 Notre Dame St. Uni Embrun, Ontario, KOA 1 Paterson Group Inc. 9 Auriga Drive	t D
	SML Construction 663 Notre Dame St. Uni Embrun, Ontario, K0A 1 Paterson Group Inc. 9 Auriga Drive Ottawa, Ontario, K2E 7	t D
Name of payment certifier:	SML Construction 663 Notre Dame St. Uni Embrun, Ontario, K0A 1 Paterson Group Inc. 9 Auriga Drive Ottawa, Ontario, K2E 7	t D IW1
Name of payment certifier:	SML Construction 663 Notre Dame St. Uni Embrun, Ontario, K0A 1 Paterson Group Inc. 9 Auriga Drive Ottawa, Ontario, K2E 7	t D IW1

1

Ottawa

North Bay