FORM 9 CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

Construction Act

City of Toronto
(County/District/Regional Municipality/Town/City in which premises are situated)
334-336 Dundas Street West, Toronto, ON
(street address and city, town, etc., or, if there is no street address, the location of the premises)
This is to certify that the contract for the following improvement:
Stair and Landing Rehabilitation
(short description of the improvement)
to the above premises was substantially performed on September 16, 2022 (date substantially performed)
Date certificate signed: September 27, 2022
In the second se
(payment certifier where there is one) (owner and contractor, where there is no payment certifier)
Name of owner: Art Gallery of Ontario Address for service: 317 Dundas Street West, Toronto, ON M5T 1G4
Name of contractor: Restorex Contracting Ltd.
Address for service: 22 Bramwin Court, Brampton, ON L6T 5G2
Name of payment certifier (where applicable): Read Jones Christoffersen Ltd.
Address: 400-100 University Avenue, Toronto, ON M5J 1V6
(Use A or B, whichever is appropriate)
334-336 Dundas Street West, Toronto, ON (if a lien attaches to the premises, a legal description of the premises, including all property identifier numbers and addresses for the premises)
B. Office to which claim for lien must be given to preserve lien:
(if the lien does not attach to the premises, the name and address of the person or body to whom the claim for lien must be given)