

November 17, 2022

Edward Welch C.E.O Brook Restoration Ltd. 11 Kelfield Street Etobicoke, ON M9W 5A1

Dear Edward Welch,

Re: Contract F60-11 Kipling Station - East Entrance Slope Stabilization Substantial Performance Letter

This is to advise you that the Work included in the above noted Contract was Substantially Performed on October 28, 2022. Enclosed for your publication is a copy of the Certificate of Substantial Performance in accordance with the Construction Act.

The existing fence repair has been deferred in the Substantial Performance calculation as agreed. Please find attached a preliminary deficiency list. Please complete all outstanding work, including but not limited to outstanding documentation, and remedy all deficiencies/incomplete work by November 27, 2022.

In accepting this work, the TTC does so on the understanding that warranty on the completed work as set out in Document 00 72 00, Article GC 10 of the Contract Documents, commenced on October 28, 2022.

Release of holdback will be made in accordance with Document 00 73 00, Articles SC 3.20 and SC 3.21 of the Contract Documents.

Sincerely,

Brian Billark

Construction Site Manager Construction Department

50-106-57

SharePoint # 03075-151817624-8

Attachments:

Certificate of Substantial Performance and Deficiency List

FORM 9 CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

Construction Act

City of Toronto ☐ ,
(County/District/Regional Municipality/Town/City in which premises are situated)
1900 Yonge Street, Toronto, Ontario, M1K 5H4
(street address and city, town, etc., or, if there is no street address, the location of the premises)
This is to certify that the contract for the following improvement:
Contract F60-11 "Kipling Station - East Entrance Slope Stabilization"
(short description of the improvement)
to the above premises was substantially performed on October 28, 2022 (date substantially performed)
Date certificate signed: November 17, 2022 Edward Welch, C.E.O. of Brook Restoration Ltd
(payment certifier where there is one) (owner and contractor, where there is no payment certifier)
Name of owner: Toronto Transit Commission
Address for service: 1900 Yonge Street, Toronto, Ontario, M1K 5H4
Name of contractor: Brook Restoration Ltd.
Address for service: 11 Kelfield Street, Etobicoke, Ontario, M9W 5A1
Name of payment certifier (where applicable):
Address:
(Use A or B, whichever is appropriate)
A. Identification of premises for preservation of liens:
(if a lien attaches to the premises, a legal description of the premises,
including all property identifier numbers and addresses for the premises)
⊠ B. Office to which claim for lien must be given to preserve lien:
Claims for Lien are to be submitted to Toronto Transit Commission electronically as directed at www.ttc.ca/liens
(if the lien does not attach to the premises, a concise description of the premises, including addresses, and the name and address of the person or body to whom the claim for lien must be given)
and the name and address of the person of body to whom the claim for lief must be given)