Form 9

Construction Act

CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

ON, Canada		
(Country/Distract/Regional Municipality/Town/City or Borough of Municipality of Metropolitan Toronto in which the Premises are situated)		
100 Bronte Rd., Oakville		
(Street Address and city, town, or if there is no street address, the location of the premises) This is to certify that the contract for the following improvement: Sloped Metal Roof Replacement, Replacement Of Rainwater Goods & Balcony Guards, Balcony Wall & Sealant Repairs And Skylight Replacement. (short description of the improvement)		
to the above premises was substantially performed on		November 18, 2022
Date Certificate Signed:	Nov 25, 2022	(date substantially performed)
(ayment cantil	where there is one)	(owner and contractor, where there is no payment certifier)
Name of owner	Halton Candominium Co	
Name of owner Halton Condominium Corporation No. 185		
Address for service	c/o CIE Property Manag 1-192 Main St. E. Milton, ON, L9T 1N8	ement & Consulting Inc.
Name of Contractor	Xcel Construction Limite	od
Address for service	255 Carrier Dr., 2nd Floor Toronto, ON, M9W 5Y8	
Name of payment certifier	Edison Engineers Inc.	
Address	17 Ogilvie St. Dundas, ON, L9H 2S1	
Halton Condominium FPL 20R-9507 (Where liens attach to premises, refer	rence to lot and plan or instrument registration	T LTS 102, 103, 104, 105 and 106 PL M11, 1 to 49 on
□ B. Office to which claim for lien and affidavit must be given to preserve lien:		