## Form 9

## **Construction Act**

## CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

Toronto, Ontario, Canada

100 York Gate Blvd., Toronto, Ontario, M3N 2C4 This is to certify that the contract for the following improvement: Balcony Repairs Including Guard Replacement. to the above premises was substantially performed on December 16, 2022 Date Certificate Signed: 2023-01-05 (owner and contractor, where there is no payment certifier) Name of owner Elm Place Inc. c/o Cherishome Living Address for service 60 Scarsdale Road, Unit #120 North York, Ontario M3B 2R7, Ontario, M3B 2R7 Name of Contractor Kingsgate Restoration Inc. Address for service 900 The East Mall, Suite 101 Etobicoke, ONTARIO, M9B 6K2 Name of payment certifier Edison Engineers Inc. Address 105 - 6 Shields Court Markham, ON, L3R 4S1

(Use A or B whichever is appropriate)

 $\hfill \Box$  A. Identification of premises for preservation of liens:

Block G Registered Plan 6530

(Where liens attach to premises, reference to lot and plan or instrument registration number)

□ B. Office to which claim for lien and affidavit must be given to preserve lien: