

Toronto Transit Commission 1900 Yonge Street, Toronto, ON M4S 1Z2 416-393-4000

June 23, 2022

Carlo Sansalone Director Sanscon Construction Ltd. 79 Fenmar Drive Toronto Ontario M9L 1M3

Dear Carlo Sansalone:

Re: Contract B65-3 Dundas West Station Loop Track Replacement Substantial Performance

This is to advise you that the Work included in the above noted Contract was Substantially Performed on June 17, 2022. Enclosed for your publication is a copy of the Certificate of Substantial Performance (FORM 9) in accordance with the Construction Act.

Please find attached a preliminary deficiency list. Please complete all outstanding work and remedy all deficiencies by July 17, 2022.

In accepting this work, the TTC does so on the understanding that warranty on the completed work as set out in Document 00 72 00, Articles GC10 of the Contract Documents, commenced on June 17, 2022.

Release of holdback and final payment will be made in accordance with Document 00 73 00 Articles SC6 of the Contract Documents.

Sincerely,

100

on Behalf of Angela Gougeon

Angela Gougeon Construction Site Manager Construction Department

50-74-167 03075-1422490166-17

Attachments: Certificate of Substantial Performance Preliminary Deficiency List

Jaye Robinson, Chair Joanne De Laurentiis, Vice-Chair Richard J. Leary, Chief Executive Officer Brad Bradford, Commissioner Shelley Carroll, Commissioner Fenton Jagdeo, Commissioner Cynthia Lai, Commissioner

Ron Lalonde, Commissioner Jennifer McKelvie, Commissioner Denzil Minnan-Wong, Commissioner Julie Osborne, Commissioner

FORM 9 Certificate of Substantial Performance of the Contract under Subsection 32 of the Act *Construction Act*

In the City of Toronto	
(County / District / Reg	jional Municipality / Town / City in which premises are situated)
The Work is located at Toronto Trans Toronto, ON M6P 1W7	sit Commission's Dundas West Station: 2365 Dundas St W,
(street address and city, to	vn, etc., or if there is no street address, the location of the premises)
This is to certify that the contract for the	following improvement:
B65-3 Dundas West Station Loop Tra	ck Replacement
	(short description of the improvement)
to the above premises was substantially	y performed on 17-Jun-22
	(date substantially performed)
Date certificate signed: 23-June-22	
	on behalf of Angela Gougeon
	Carlo Sansalon
(payment certifier where there is one)	(owner and contractor, where there is no payment certifier)
Name of owner: Toronto Transit Com	mission
Address for service: 1900 Yonge St	rret, Toronto, Ontario M4S 1Z2
Name of contractor: Sanscon Cons	truction Ltd.
Address for service: 79 Fenmar Dr ,	North York, ON M9L 1M3
Name of payment certifier (where applic	able):
Address:	
(Use A or B, whichever is appropriate)	
A. Identification of premises for prese	rvation of liens:
	es to the premises, a legal description of the premises, perty identifier numbers and addresses for the premises)
☑B. Office to which claim for lien and a	ffidavit must be given to preserve lien:
	o Toronto Transit Commission electronically as directed at
	a promises a consist description of the promises, including addresses

(if the lien does not attach to the premises, a concise description of the premises, including addresses, and the name and address of the person or body to whom the claim for lien must be given)



Contract Deficiency List

June 20, 2022 Issue Date

Rev No.	Contract Name / Number	Anticipated Contract Completion Date									
0	Dundas West Station Loop Track Replacement/B65-3	July 17, 2022									
ltem	Description	Location	Туре	Status	Date Identified	Identified by	Committed Date	Date Closed	Estimated Cost of Deficient Work	Previous Comments	New Comments
1	Detectable Safety Warning Edge tiles installation	Along Platform Edge	Incomplete	Issued	17-Jun-2022	SCI	16-Jul-2022		\$15,000.00		
2	Lighting pole footings and center platform structure	Center Platform	Incomplete	Issued	16-Jun-2022	SCI	8-Jul-2022		\$10,000.00		
3	Routing and sealing of asphalt joints	Station Loop	Incomplete	Issued	17-Jun-2022	SCI	8-Jul-2022		\$1,000.00		
4	New pavement markings	Around and inside station	Incomplete	Issued	17-Jun-2022	SCI	15-Jul-2022		\$2,500.00		
5		South to Intersection of Dundas/ Roncesvalles	Incomplete	Issued	17-Jun-2022	SCI	15-Jul-2022		\$50,000.00		
6	Lighting pole and associated conduit/wire, lighting fixture	sT8 pole	Incomplete	Issued	17-Jun-2022	SCI	17-Jul-2022		\$10,000.00		
	Post-construction power wash and video tapping of storm system.	Storm system	Incomplete	Issued	17-Jun-2022	SCI	15-Jul-2022		\$3,000.00		
8	Building permit and ESA inspections	N/A	Incomplete	Issued	17-Jun-2022	SCI	4-Jul-2022		\$2,000.00		
9	Commissioning	N/A	Incomplete	Issued	17-Jun-2022	SCI	15-Jul-2022		\$10,000.00		
10	As-Built drawings	N/A	Incomplete	Issued	17-Jun-2022	SCI	15-Jul-2022		\$2,000.00		
11	Outstanding submittals	N/A	Incomplete	Issued	17-Jun-2022	SCI	15-Jul-2022		\$1,000.00		
TOTAL VALUE \$106,500.00											