

CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT

THE CITY OF TORONTO

(County / District or Regional Municipality / City or Borough In which premises are situate)

519 CHURCH STREET, TORONTO, ONTARIO

(Street address and City, Town etc., or , if there is no street address, the location of the premises)

This is to certify that the contract between

BROOK RESTORATION LTD

and

THE CITY OF TORONTO

Dated February 9, 2022, with respect to the following scope of work:

Foundation Waterproofing, Stair Enclosure, Various Repairs, State of Good Repairs at
519 Church Street, Toronto, Ontario


(Short description of the improvement)

to the above premises was substantially performed on May 3rd, 2023.

(Date Substantially Performed)

May 5th, 2023

Date Certificate Signed


Name and Signature of Certifier

Name of Owner : The City of Toronto
Address for Service : 18TH Floor, West Tower, 100 Queen St W
Toronto, Ontario, M5H 2N2

Name of Contractor : Brook Restoration Ltd.
Address for Service : 11 Kelfield St
Toronto, Ontario, M9W 5A1

Name of Payment Certifier : Tabcon Consulting Inc.
Address for Service : 494 McNicoll Avenue, Suite # 201
Toronto, Ontario, M2H 2E1

(Use A or B whichever is appropriate)

A.-

(Identification of premises for Preservation of Liens)

B.-

519 Church Street, Toronto, Ontario

(Office to which claim for lien and affidavit must be given to preserve Lien)

Certifier's Company Seal

