

9 Auriga Drive Ottawa, Ontario Canada K2E 7T9 Tel: (613) 226-7381

Geotechnical Engineering Environmental Engineering Hydrogeology Materials Testing Building Science

Rural Development Design Retaining Wall Design Noise and Vibration Studies

CERTIFICATE OF SUBSTANTIAL PERFORMANCE

OF THE CONTRACT UNDER SECTION 32 OF THE CONSTRUCTION LIEN ACT

patersongroup.ca

1.	City of Ottawa		
	(County, District or Regional Municipality, City	or Borough)	
2.	71 Somerset Street West, Ottawa Ontario		
	(Street address and city, town etc., or, if there is no street address, the location of the premises)		
3.	This is to certify that the contract for the following improvement:		
	Phase 3 Window & Patio Door Replacement at Carleton Condominium Corporation No. 74		
	(short description of the improvement)		
	To the above premises was sub-	stantially performed on:	July 24, 2023
4.	Name of owner:	Carlton Condominium Corporation No. 74	
	Address for service:	% Condominium Management Group	
		434 Queen Street, Ottawa, Ontario, K1R 7V7	
5.	Name of contractor:	Lor-Issa Construction Inc.	
		3140 Carp Road	
		Carp, Ontario, K0A 1L0	
6.	Name of payment certifier:	Paterson Group Inc.	
		9 Auriga Drive	
		Ottawa, Ontario, K2E 7T9	
7.	Identification of premises for preservation of liens:		CCC No. 74: 71 Somerset Street West
			Ottawa, Ontario, K2P 2G2
8.	Recommended by consultant:	danta	Date: July 24, 2023
	Christopher Lyons, A.Sc.T.		