

**FORM 9**  
**CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE**  
**CONTRACT UNDER SECTION 32 OF THE ACT**

*Construction Act*

**City of Brampton**

(County/District/Regional Municipality/Town/City in which premises are situated)

**37 Eastbourne Drive, Brampton, Ontario**

(street address and city, town, etc., or, if there is no street address, the location of the premises)

This is to certify that the contract for the following improvement:

**Targeted and Localized Repair of the Exterior Walls**

(short description of the improvement)

to the above premises was substantially performed on **October 30, 2023**

(date substantially performed)

Date certificate signed: **November 1, 2023**

(payment certifier where there is one)

(owner and contractor, where there is no payment certifier)

Name of owner: **Brampton Park Acquisitions  
Corporation c/o Greenwin Inc.**

Address for service: **19 Lesmill Road, North York, Ontario M3B 2T3**

Name of contractor: **Aztec Structural Restoration Inc.**

Address for service: **Unit 1- 11 Holland Drive, Bolton, Ontario L7E 7G4**

Name of payment certifier (where applicable): **Momentum Engineering  
Management Inc.**

Address: **Suite 100, 400 Applewood Crescent, Vaughan, Ontario L4K 0C3**

(Use A or B, whichever is appropriate)

☒ A. Identification of premises for preservation of liens:

**37 Eastbourne Drive, Brampton, Ontario**

(if a lien attaches to the premises, a legal description of the premises,  
including all property identifier numbers and addresses for the premises)

☐ B. Office to which claim for lien must be given to preserve lien:

(if the lien does not attach to the premises, a concise description of the premises, including addresses,  
and the name and address of the person or body to whom the claim for lien must be given)