## CRITCHLEY HILL

## FORM 9- Construction Act CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

Location of the Work:
District of Kenora, Municipality of Sioux Lookout, Ontario  (County/District of Regional Municipality/City of Borough of Municipality of Metropolitan Toronto in which Premises are situated)  86 3rd Ave N, Sioux Lookout, ON P8T 1A9  (Street address and city, town, etc., or, if there is no street address, the location of the Premises)
Certification:
This is to certify that the contract for the following improvement:
Sioux North HS – Deficiency Rectification Work (Short description of the improvement)
To the above Premises was substantially performed on August 31, 2023
November 1, 2023  Date certificate signed  Signature of Payment Certifier
Signature of Owner Signature of Contractor (where there is no certifier) (where there is no certifier)
Parties:
Owner:  Name: Keewatin Patricia District School Board
Address for service: 40. Veterans Drive, Kenora, ON P9N 3Y5
Contractor:  Name: Finn Way General Contractors Inc.
Address for service: 1301 Walsh St W, Thunder Bay, ON P7E 4X6  Payment Certifier: (where applicable)
Name: Critchley Hill Architecture Inc.
Address for service: 123 McIntyre St W, North Bay, ON P1B 2Y5
Registration for Liens: (Use A or B whichever is appropriate)
Identification of premises for preservation of liens
86 3rd Ave N, Sioux Lookout, ON P8T 1A9 (where liens attach to premises, reference to lot, plan or instrument registration number)
B. Office to which claim for lien and affidavit must be given to preserve lien
(where liens do not attach to premises)