Construction Act

R.S.O. 1990, Chapter C.30 Last Amendment: 2018, C.17, Sched. 8, S.1-20

CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

CITY OF HAMILTON

100 KING STREET WEST HAMILTON, ONTARIO

This is to certify that the Contract for the following improvement:

WEATHERED PANEL REPAIRS

to the above premises was substantially performed on November 27, 2023

Date certificate signed: November 27, 2023

(Payment Certifier)

Name of Owner:

FIRST REAL PROPERTIES LTD.

Address of Service:

100 King Street West, Plaza Level

Hamilton, Ontario, L8P 1A2

Name of Contractor:

PALMARK CONSTRUCTION LTD.

Address for Service:

44 Haas Road

Etobicoke, Ontario, M9W 3A2

Name of Payment Certifier: READ JONES CHRISTOFFERSEN LTD.

Address:

100 University Avenue, North Tower, Suite 400

Toronto, ON, M5J 1V6

Identification of premises for preservation of liens: A.

100 KING STREET WEST, HAMILTON, ONTARIO