#### Construction Act

R.S.O. 1990, Chapter C.30 Last Amendment: 2018, C.17, Sched. 8, S.1-20

## CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

## HAMILTON, ONTARIO

# 100-120 KING STREET WEST, HAMTILON, ONTARIO

This is to certify that the Contract for the following improvement:

### 2022 VARIOUS SITE REPAIRS

to the above premises was substantially performed on February 1, 2024

Date certificate signed: February 22, 2024

(Payment Certifier)

Name of Owner:

FIRST REAL PROPERTIES LTD.

Address of Service:

100 King Street West, Plaza Level

Hamilton, Ontario, Canada L8P 1A2

Name of Contractor:

PALMARK CONSTRUCTION LTD.

Address for Service:

44 Haas Road

Etobicoke, Ontario M9W 3A2

Name of Payment Certifier: **READ JONES CHRISTOFFERSEN LTD.** 

Address:

100 University Avenue, North Tower, Suite 400

Toronto, ON, M5J 1V6

A. Identification of premises for preservation of liens:

100-120 KING STREET WEST, HAMTILON, ONTARIO