



CONCENTRIC

CLIENT-CENTRIC. CHALLENGE DRIVEN.

LONDON, ONTARIO

700 Richmond Street, Suite 307
London, ON N6A 5C7

T 519.452.7700 **F** 519.452.1712
TF 1.866.919.4531

OTTAWA, ONTARIO

2327 St. Laurent Boulevard, Unit 100
Ottawa, ON K1G 4J8

T 613.824.8900 **F** 613.824.8901
TF 1.866.919.4530

SASKATOON, SASKATCHEWAN

3530 Millar Avenue, Unit 400
Saskatoon, SK S7P 0B6

T 306.343.5500 **F** 306.343.3601
TF 1.866.919.8899

IQALUIT, NUNAVUT

P.O. Box 957
Iqaluit, NU X0A 0H0

T 867.979.3300 **F** 867.979.3302
TF 1.866.919.4533

Our File: 24-9757

May 3, 2024

Waterdon Construction Services
29 Cleopatra Drive
Ottawa, Ontario
K2G 0B6

Attn: Mr. Shayne Benoit Project Manager

**Re: National Gallery of Canada-Main Kitchen Flooring
Replacement Certificate of Substantial Completion**

Dear Shayne,

Enclosed is the certificate of substantial completion performance for the above noted project.

Based on the work completed to date, we are recommending to National Gallery of Canada that the project is substantially complete.

Waterdon Construction Services is required to publish this certificate of substantial completion in the Commercial Daily News in accordance with the Construction Lien Act. We request a copy published certificate for our records

Should there be any questions, please contact the undersigned.

Yours sincerely,

CONCENTRIC

Paul Matergio, C.E.T.
Partner

c.c. by email: Mr. Joseph Nguyen-jnguyen@gallery.ca

FORM 9
CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE
CONTRACT UNDER SECTION 32 OF THE ACT

Construction Act

Ottawa, Ontario

(County/District/Regional Municipality/Town/City in which premises are situated)

380 Sussex Drive, Ottawa, Ontario, K1N 9N4

(street address and city, town, etc., or, if there is no street address, the location of the premises)

This is to certify that the contract for the following improvement:

National Gallery of Canada Main Kitchen Flooring Replacement Program

(short description of the improvement)

to the above premises was substantially performed on:

May 2, 2024

(date substantially performed)

Date certificate signed:

May 3, 2024

(payment certifier where there is one)

(owner and contractor, where there is no payment certifier)

Name of owner: **National Gallery of Canada**

Address for service: **380 Sussex Drive, Ottawa, Ontario, K1N 9N4**

Name of contractor: **Waterdon Construction Services**

Address for service: **29 Cleopatra Drive, Ottawa, Ontario, K2G 0B6**

Name of payment certifier (where applicable): **Paul Matergio**

Address: **100-2327 St Laurent Boulevard, Ottawa, Ontario, K1G 5J1**

(Use A or B, whichever is appropriate)

A. Identification of premises for preservation of liens:

National Gallery of Canada 380 Sussex Drive, Ottawa, Ontario K1N 9N4

(if a lien attaches to the premises, a legal description of the premises,
including all property identifier numbers and addresses for the premises)

B. Office to which claim for lien must be given to preserve lien:

(if the lien does not attach to the premises, the name and address of the person or body to whom the claim for lien must be given)