Construction Act

R.S.O. 1990, Chapter C.30 Last Amendment: 2018, C.17, Sched. 8, S.1-20

CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

CITY OF TORONTO

69 LYNN WILLIAMS STREET TORONTO, ONTARIO

This is to certify that the Contract for the following improvement:

NORTH PLANTER BED REPAIRS

to the above premises was substantially performed on AUGUST 16 2024

Date certificate signed: August 26, 2024

、 、	
(D)	C
(Payment	(priitier)
(I dryntent	certifier

Name of Owner:	Crossbridge Condominium Services Agents for and on behalf of TSCC 2325/TSCC 2371 Shared Facilities
Address of Service:	69 Lynn Williams Street Toronto, ON M6K 3R7
Name of Contractor:	Eagle Restoration Inc.
Address for Service:	19 Meteor Drive Toronto, ON M9W 1A3
Name of Payment Certifier:	Read Jones Christoffersen Ltd.
Address:	100 University Avenue, North Tower, Suite 400 Toronto, ON M5J 1V6

Identification of premises for preservation of liens: A.

69 Lynn Williams St, Toronto, ON M6K 3R7