BUILDING SCIENCES AND ENGINEERING

Form 6 - Construction Lien Act, 1983

CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT

(Country/District or Regional Municipality/City or Borough of Metropolitan Toronto in which premises are situated)

Scarborough, Ontario

(Street Address and City, Town, etc. or, if there is no street address, the location of the premises)

55 Livingston Road, Scarborough, Ontario

This is to certify that the contract for the following improvement:

GARAGE RAMP RESTORATION AND SNOW MELTING EQUIPMENT REPAIRS

(short description of the improvement)

to the above premises was substantially performed on:

July 22, 2020

(date substantially performed)

Ontech Building Consultants Inc.

Date Certificate signed: July 22, 2020

Consultant:

(Payment Certifier where applicable)

N/A

Owner:

N/A

Contractor:

(Owner and Contractor, where there is there is no Payment Certifier)



www.ontechbuildingconsultants.com

BUILDING SCIENCES AND ENGINEERING

Form 6 - Construction Lien Act, 1983	
	CERTIFICATE OF SUBSTANTIAL PERFORMANCE OF THE CONTRACT UNDER SECTION 32 OF THE ACT
Name of Owner:	
PARK PROPERTY MANAGEMENT INC.	
Address of Service:	
55 Livingston Road, Scarborough, Ontario	
Name of Contractor:	
Solar Restoration Inc.	
Address of Contractor:	
3 Miller Street Toronto, Ontario M6N 2Z6	
Name of Payment Certifier: (where applicable)	
Ontech Building Consultants Inc.	
Address of Payment Certifier:	
138 Cedric Avenue Toronto, Ontario M6C 3X8	
(Use A or B, whichever is appropriate)	
A.	Identification of premises for preservation of liens:
	55 Livingston Road, Scarborough, Ontario
	(where liens attach to premises, reference to lot and plan or instrument registration number)
B.	Office to which claim for lien and affidavit must be given to preserve lien:

(where liens do not attach to premises)