

**CERTIFICATE OF SUBSTANTIAL PERFORMANCE
OF THE CONTRACT UNDER SECTION 32 OF THE ACT**

City of Hamilton, Ontario

(County/District or Regional Municipality or City in which premises are situate)

192 Hudson Street North, Hamilton, Ontario

(Street address and city, town, etc., or, if there is no street address, the location of the premises)

This is to certify that the contract for the following improvement:

Repair of Underground Parking Garage Roof Slab & Ramp Slab

(short description of the improvement)

to the above premises was substantially performed on

September 01, 2020

(date substantially performed)

Date certificate signed: September 26, 2020



(payment certifier where there is one)

*(owner and contractor, where there is
no payment certifier)*

Name of owner: Greenwin Corp.

Address for service: 192 Hudson Street North, Hamilton

Name of contractor: Brook Restoration Ltd.

Address for service: 11 Kelfield Street, Etobicoke, Toronto

Name of payment certifier: CCE Group Ltd.

(where applicable)

Address: 3080 Yonge Street, Suite 6060, Toronto, M4N 3N1

(Use A or B whichever is appropriate)

A. Identification of premises for preservation of liens:

192 Hudson Street North, Hamilton, ON

(where liens attach to premises, reference to lot and plan or instrument registration number)

B. Office to which claim for lien and affidavit must be given to preserve lien:

(where liens do not attach to premises)