

Burlington, Ontario

(County/District/Regional Municipality/Town/City in which premises are situated)

2050 Upper Middle Road

(street address and city, town, etc., or, if there is no street address, the location of the premises)

This is to certify that the contract for the following improvement:

Garage Roof Deck Restoration

(short description of the improvement)

to the above premises was substantially performed on

November 26, 2020

(date substantially performed)

Date certificate signed: December 3, 2020



(payment certifier where there is one)

Paul Nasato

(owner and contractor, where there is no payment certifier - signatures required)

Name of Owner

Halton Condominium Corporation #80

Address for Service

c/o CIE Property Management & Consulting Inc.

1 - 192 Main Street East

Milton, ON, L9T 1N8

Name of Contractor

Brook Restoration Ltd.

Address for Service

11 Kelfield St., Etobicoke, ON M9W 5A1

Name of Payment

Cion Coulter Corp.

Certifier

(where applicable):

Address

920 Brant Street, Suite 22, Burlington, Ontario L7R 4J1

(Use A or B whichever is appropriate)

A. Identification of premises for preservation of liens:

Halton Condominium Corporation #80 - 2050 Upper Middle Road, Burlington, Ontario

(if a lien attaches to the premises, a legal description of the premises, including all property identifier numbers and addresses for the premises)

B. Office to which claim for lien must be given to preserve lien:

(if the lien does not attach to the premises, the name and address of the person or body to whom the claim for lien must be given)