

CERTIFICATE OF SUBSTANTIAL PERFORMANCE



CLELAND
JARDINE
ENGINEERING LTD

PROJECT Overbrook Community – Front and Rear Canopy Repairs

CONTRACTOR Brook Restoration Ltd.

PROJECT No. 21-1242

1. **Ottawa, Ontario**

County, District or Regional Municipality or Borough

2. This is to certify that the following improvement,

Front and Rear Canopy Repairs – Phase 1

Overbrook Community

Ottawa, Ontario

to the above premises was deemed substantially performed on: **September 14th, 2022**

3. Owner's Representative: **Ottawa Community Housing Corporation**

Address for Service:

39 Auriga Drive

Ottawa, Ontario, K2E 7Y8

4. Contractor:

Brook Restoration Ltd.

Address for Service:

1520 Lagan Way

Ottawa, Ontario, K1B 3S9

5. Payment Certifier:

Cleland Jardine Engineering Ltd.

Address for Service:

580 Terry Fox Drive, Suite 200

Ottawa, Ontario, K2L 4B9

6. Identification of premises for preservation of liens: **Ottawa Community Housing Corporation**

Overbrook Community

Ottawa, Ontario

7. Recommended by

Consultant:

*Cassie Cullimore, M.Sc., EIT
Building Specialist, Building Science Dept.*

September 19th, 2022

Date