

CERTIFICATE OF SUBSTANTIAL PERFORMANCE



CLELAND
JARDINE
ENGINEERING LTD

PROJECT Overbrook Community – Front and Rear Canopy Repairs

CONTRACTOR Brook Restoration Ltd.

PROJECT No. 21-1242

1. **Ottawa, Ontario**

County, District or Regional Municipality or Borough

2. This is to certify that the following improvement,

Front and Rear Canopy Repairs – Phase 2

Overbrook Community

Ottawa, Ontario

to the above premises was deemed substantially performed on: **September 14th, 2022**

3. Owner's Representative: **Ottawa Community Housing Corporation**

Address for Service: **39 Auriga Drive**

Ottawa, Ontario, K2E 7Y8

4. Contractor: **Brook Restoration Ltd.**

Address for Service: **1520 Lagan Way**

Ottawa, Ontario, K1B 3S9

5. Payment Certifier: **Cleland Jardine Engineering Ltd.**

Address for Service: **580 Terry Fox Drive, Suite 200**

Ottawa, Ontario, K2L 4B9

6. Identification of premises for preservation of liens: **Ottawa Community Housing Corporation**

Overbrook Community

Ottawa, Ontario

7. Recommended by
Consultant:

*Cassie Cullimore, M.Sc., EIT
Building Specialist, Building Science Dept.*

September 19th, 2022

Date